



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 7478R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DENTED	2,886.50	2,542.65
1	REAR BUMPER TOW COVER -RH (CONSISTENT)	NOT NECESSARY	48.50	-
2	REAR BUMPER PDC SENSOR @\$291.55 (CONSISTENT)	SHORTED (1 PCS ONLY)	583.10	291.55
1	REAR BUMPER DIFUSSER (CONSISTENT)	NOT NECESSARY	691.60	-
1	REAR BUMPER GUIDE -CTR (CONSISTENT)	NOT NECESSARY	221.50	-
2	REAR BUMPER GUIDE -RH/LH @\$135.00 (CONSISTENT)	O/S CRACKED	270.00	135.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	1,195.00	831.00
1	REAR BOOT LID (CONSISTENT)	TO REPAIR SEE LABOUR	2,950.90	-
1	REAR BOOT CHROME MOULDING (CONSISTENT)	NOT NECESSARY	831.50	-
1	REAR BOOT EMBLEM INSIGNIA (CONSISTENT)	NECESSARY	121.50	121.50
1	REAR BOOT EMBLEM CDTI (CONSISTENT)	NECESSARY	89.50	89.50
1	REAR BOOT LAMP -RH (CONSISTENT)	NOT NECESSARY	510.60	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	231.50	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	955.00	-
1	REAR TAILLAMP -RH (CONSISTENT)	CRACKED	1,590.00	1,099.20
1	REAR TAILLAMP PANEL -RH (CONSISTENT)	TO REPAIR SEE LABOUR	235.00	-
	LESS 10% DISCOUNT		-1,341.17	-511.04
			12,070.53	4,599.36
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER GUIDE REVERT PLUG (SN) (CONSISTENT)	NECESSARY	120.00	60.00
1	SET BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			170.00	110.00
<b><u>LABOUR</u></b>				
	TO CHECK REAR WIRING.		50.00	20.00
	TO REMOVE AND REFIX REAR INTERIOR TRIMS .	NOT NECESSARY	120.00	-
	TO TUFF KOTE.	NOT NECESSARY	60.00	-
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS.		1,080.00	700.00

Report Ref No. CC4/HSB23001458/Upa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID ,REAR END PANEL AND REAR TAILLAMP PANEL -RH.		900.00	450.00
			2,210.00	1,170.00
<b>GRAND TOTAL</b>			<b>14,450.53</b>	<b>5,879.36</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,700.00</b>

Report Ref No. CC4/HSB23001458/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.