



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8859K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,280.20	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	60.00	-
1	FRONT BUMPER LAMP - LH	SERVICEABLE	205.10	-
1	FRONT BUMPER LAMP COVER	SERVICEABLE	95.20	-
1	FRONT BUMPER LOWER GARNISH - LH	SERVICEABLE	215.50	-
1	FRONT BUMPER SIDE RETAINER - LH	SERVICEABLE	97.20	-
1	FRONT FENDER - LH	TO REPAIR SEE LABOUR	747.00	-
1	FRONT FENDER ARCH GARNISH	CUT	265.20	265.20
1	FRONT FENDER INNER SHIELD - LH	SERVICEABLE	225.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS - LH	NOT NECESSARY	80.00	-
1	HEAD LAMP - LH	SERVICEABLE	1,975.15	-
	LESS 25% DISCOUNT		-	-66.30
			5,245.55	198.90
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER - LH.		1,200.00	150.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,000.00	220.00
	TO APPLY RUST- PROOFING ON REPAIRED. REPLACED PANEL.	NOT NECESSARY	80.00	-
	TO CHECK WIRING FUNCTIONS.	NOT NECESSARY	50.00	-
			2,330.00	370.00
GRAND TOTAL			7,575.55	568.90
RECOMMENDED COST OF REPAIRS				568.90

Report Ref No. CS/SMR23001463/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.