

MS First Capital Insurance Ltd

6507 3848

SHIFTER AUTO GARAGE PTE. LTD.

Co. Reg. No: 202230804K 3016 Bedok North Avenue 4 #07-04 Eastech

Singapore 489947

Email: shifterauto.sag@gmail.com

TAX INVOICE

Invoice No.

: SAG2023 43 02

Invoice Date : February 01, 2023

Vehicle No.

: S∐4171T

Make & Model: Toyota Allion

Chassis No.

: NZT2603032962

Mileage

Terms

: Due within 90 days

NO.	DESCRIPTION	QUANTITY	PER UNIT (SGD)	AMOUNT (SGD)
1	To Carry Out Repair & Respray on Accident	1	7,000.00	7,000.00
	Corresponding to Supply on Spare Parts & Labour			
	Charges			

GRAND TOTAL:	\$7,000.00
Amount Paid	\$0.00
Balance Due	\$7,000.00

company Stamp

I agree to the price as listed above and affirm that the goods are received in good condition.

CARS FOR RENT (2016) PTE LTD

Mailing Address:

10 Kaki Bukit Ave 4 #09-60 Premier@Kaki Bukit, Singapore 415874

Tel Nos.: +65 6970 9119 / 6789 5155

Co. Reg'n No.: 201609732N GST Reg'n No.: 201609732N Tax Invoice #: E2212170

Date: 20-12-22

1

Bill To:

Shifter Auto Garage Pte Ltd For the account of: Yu Zhao Yuan Pte Ltd UEN: 201004146Z 260 Geylang Road 389316

Ship To:

Shifter Auto Garage Pte Ltd For the account of: Yu Zhao Yuan Pte Ltd UEN: 201004146Z 260 Geylang Road 389316

Description

Amount

Job No.

Vehicle Rental for Period 03.12.2022 to 16.12.2022 (Billing for days 13 X \$120.00/per day) (Vehicle No.: SLJ4171T)

\$1,560.00 SDG4840G SR



Your Order #: 21249

SR

RATE

Terms: Net 30th after

GST SALE AMOUNT

Total Inv Amt:

GST:

\$102.06 \$1,560.00

\$0.00

Balance Due:

\$1,560.00

COMMENT

CODE

7%

\$102.06

\$1,457.94 Amount Applied:



Driving Licence No: G6450 786 PD/L Type: Local / International

16 DEC 2010.

260 Genlang Road

HP

D/L Type: Local / International

VEHICLE CHECK LIST

CARS FOR RENT (2016) PTE LTD

10 Kaki Bukit Ave 4 #09-60 Premier @ Kaki Bukit Singapore 415874 Tel: 6970 9119 Fax: 6970 9961 Website: www.carsforrent2016.com

No: 21249

ROC/GST No: 201609732N HIRER'S PARTICULAR

NRIC/PASSPORT No: Date of Birth: Address (Res):

Issue Date:

Company Name: Company UEN:

Company Address: __

Name: (as in I/C) NRIC/PASSPORT No:

Driving Licence No:

Date of Birth: Address (Res):

Issue Date: Tel: (O)

Tel: (O)_

Name: (as in I/C) He Chuntie

IDDITIONAL DRIVER'S PARTICULARS

VEHICLE REI

N.	TAL	. AG	REE	MEN	IT	(R	7	7 3/10
	Veh	nicle No	: SD(148	10/4	Rep	lace Ve	h No:SL	541717
-		eage ou							
-	Mal	ke & Mo			A AL	TIS.		Auto / Mar	nual
	OU.	T : Date	3/15	1/20	22 *	Time	:	12 · 00pn	n.
	HIR	E PERI	OD				-1		**
	OW	N DAM	AGE CL	AIM	Exce	ess S\$		2,00	00
-	THIE	RD PAF	RTY CLA	MM	Exce	ess S\$		1.50	0
-			_	CHAR	GES				
	Daily	1	<u>}</u> @\$	120	W.	per day	/	1,360	00
	Wee	kly	@\$			per we	ek		
-	Mon	thly	@\$			per mo	nth		
	Othe	rs	@\$				1111,0		
	Deliv	ery Ser	vice						
	GST						100	L-u-	
L						SUB-TO	TAL \$		
-	PETF	ROL LE	VEL			of c			
L	Out	Е	1/4	1/2	3/4	F		I TOUR TO	
L	In	Ε	1/4	1/2	3/4	F			
-	EXTE	NSION							
1	Misc.								HAT:
(SST				Jr	F Di	0 0		
	130				тот	AL CHAF	RGES	1,560	00

A - ACCIDENTS INDICATE **FRONT** TOP LEFT

BACK

I have read and agree to the terms and condition on both sides of ths agreement. If I have presented a charge/ credit card for payment, I agree that all amount payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CARS FOR RENT (2016) PTE LTD in

* IMPORTANT

- 1. ONLY PERSON ABOVE 22 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. 2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- 3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN ABOVE.
- 4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY AND BE RESPONSIBLE FOR THE INSURANCE EXCESS. IF THERE IS BODILY INJURIES, POLICE REPORT MUST BE MADE.

Rented out by:

Hirer's Signature

Addition Driver's Signature

5. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF CARS FOR RENT (2016) PTE LTD

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVE" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CARDS FOR RENT (2016) PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	M
16/12/12	6/100				A BAR
	S desirables	de la constant			HIRER'S SIGNATURE

22 Upper Serangoon Crescent #16-53 Singapore 534025

Company Registration No. 53127785B

 Our Ref: Allied/TP/22-12004
 Veh No
 : SLJ 4171 T

 Date Report
 :
 11-Jan-23

 Repairer
 :
 Shifter Auto Garage Pte Ltd
 Date of Accident
 :
 1-Dec-22

 Address of Inspection
 Date of Survey
 :
 11-Dec-22

3016 Bedok North #07-04 Eastech

Singapore 489947

VEHICLE PARTICULARS & CONDITION

 Make & Model
 :
 Toyota Allion 1.5 A
 Date of Registration
 :
 14-Oct-08

 Engine No
 :
 1NZD196874
 Engine c.c.
 :
 1496 cc

 Chassis No
 :
 NZT2603032962
 COE Expiry Date
 :
 13-Oct-23

CONDITION OF VEHICLE

General Condition Good Modification No Air-Conditioner Steering Serviceable Yes Handbrake Serviceable Serviceable Footbrake Wing Mirror Yes Paint Work Good

CONDITION OF TYRES (The below values represent the remaining tyre treads depth)


Front Tyre Size 195/65R15 Rear Tyre Size 195/65R15 : : Front Left Side 6mm Falken Rear Left Side Windforce 6mm Front Right Side 6mm Goodyear Rear Right Side 6mm Yokohama

GENERAL DESCRIPTION OF DAMAGE

The inspected vehicle sustained damage at the **REAR** portion.

During visual inspection, our surveyor noted that the trunk lid, rear end panel, taillamps, rear bumper and among other parts were affected.

All stated damage is subject to consistency of the accident reports.



Repairer Estimate Our Recommendation

 Parts
 : 6,288.45
 Parts : 5,860.05

 Nett Item
 : 1,080.00
 Nett Item : 785.00

 Labour
 : 2,590.00
 Labour : 2,140.00

 Total
 : 9,958.45
 GST (7.00%) :

Total : 8,785.05 Less 20% : 1,757.01 7,028.04

Lump Sum (Estimated): 7,000.00

The repairer agree to repair the vehicle on a **Lump Sum Basis** with our recommendation of **SGD 7,000.00 (SGD Seven Thousand only)** and we are in the opinion the repairer would need about a **8.0** working day period to repair the vehicle.

Allied Auto Appraisal Surveyed by Ng Heng Chai
Licensed Appraiser

VECOIV	1MENDED PARTS				
No.	Descriptions	Condition	Qty	Repairer	Adjusted
1	TRUNK LID	Badly Dented	1	1,180.00	970.00 🗸
2	TRUNK LID TOYOTA BADGE	Necessary	1	112.90	112.90 🗸
3	TRUNK LID OUTER CHROME MOULDING	Dented/Cracked	1	295.90	295.90 🗸
4	TRUNK LID LICENSE PLATE LAMP (RH)	Broken	1	85.10	85.10 🗸
5	TRUNK LID LICENSE PLATE LAMP (LH)	Broken	1	85.10	85.10 🗸
6	TRUNK LID ALLION EMBLEM	Necessary	1	97.90	97.90 ✓
7	TRUNK LID A15 EMBLEM	Necessary	1	101.90	101.90 🗸
8	TRUNK LID LOCK ASSEMBLY	Dented/Cracked	1	271.00	225.90 🗸
9	TRUNK COMPARTMENT SIDE TRIM LINING (RH)	Crumpled/Deformed	1	475.90	425.90 × nn
10	TRUNK COMPARTMENT SIDE TRIM LINING (KIT) TRUNK COMPARTMENT SIDE TRIM LINING (LH)	Deformed/Torn	1	475.90	425.90 X nn
11	REAR END PANEL	Badly Dented	1	712.90	675.90 🗸
12	REAR END PANEL INNER GARNISH	Dented/Deformed	1	255.90	225.90 🗸
13	TRUNK LID WEATHERSTRIP	Torn	1	275.00	275.00 🗸
14	REAR COMBINATION LAMP (RH)	Broken	1	715.00	685.00 × nn
15	REAR COMBINATION LAMP (LH)	Broken	1	715.00	685.00 × nn
16	REAR SMART KEYLESS ANTENNA	Cracked/Broken	1	221.90	221.90 🗸
17	REAR BUMPER FACE	Dented/Cracked	1	815.00	780.00 🗸
18	REAR BUMPER REFLECTOR (RH)	Broken/Dislodged	1	102.90	102.90 🗸
19	REAR BUMPER REFLECTOR (LH)	Cracked/Broken	1	102.90	102.90 🗸
20	REAR BUMPER ARM (RH)	Badly Dented	1	197.50	197.50 🗸
21	REAR BUMPER SIDE RETAINER (RH)	Cracked	1	89.50	89.50 🗸
22	REAR BUMPER SIDE RETAINER (LH)	Cracked	1	89.50	89.50 🗸
23	EXHAUST SILENCER ASSEMBLY	Repair	1	910.00	855.90 × nn
		Sub Total (S\$)	: -	8,384.60	^{7,813.40} 4632
		Discount (25%)		2,096.15	1,953.35 -25 %
		Total Parts (S\$)	_	6,288.45	5,860.05 3474
ECON	MMENDED SPECIAL NETT ITEMS		_		3474
No.	Descriptions	Condition		Popairor	Adiustad
	Descriptions	Condition		Repairer	Adjusted
1	TRUNK LID INNER SEALER	Necessary		100.00	60.00 30
1	TRUNK LID INNER SEALER	Necessary		100.00	60.00 30 80.00 15
1 2	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS	Necessary Necessary		100.00 100.00	60.00 30 80.00 15 80.00 × nn
1 2 3 4	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS	Necessary Necessary Necessary Necessary		100.00 100.00 100.00 150.00	60.00 30 80.00 15 80.00 × nn 100.00 30
1 2 3 4 5	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS	Necessary Necessary Necessary Necessary Necessary		100.00 100.00 100.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15
1 2 3 4	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS	Necessary Necessary Necessary Necessary		100.00 100.00 100.00 150.00 80.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30
1 2 3 4 5 6	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS	Necessary Necessary Necessary Necessary Necessary	_	100.00 100.00 100.00 150.00 80.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15
1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS	Necessary Necessary Necessary Necessary Necessary		100.00 100.00 100.00 150.00 80.00 100.00 450.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200
1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS	Necessary Necessary Necessary Necessary Necessary		100.00 100.00 100.00 150.00 80.00 100.00 450.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200
1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00
1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted
1 2 3 4 5 6 7 ECON No.	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND RE	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted
1 2 3 4 5 6 7 ECON No.	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS IMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 30 325.00 30 325.00 200 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30
1 2 3 4 5 6 7 ECON No.	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND RE DAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 30 325.00 30 325.00 200 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30 325.00 30
1 2 3 4 5 6 7 ECON No.	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 ✓ 120.00 50
1 2 3 4 5 6 7 ECON No. 1	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NOT TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL.	_ _	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 325.00 32 Adjusted 900.00 ✓ 120.00 50
1 2 3 4 5 6 7 ECON No. 1 2	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND RED DAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TAILGATE.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO	_ _	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 120.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 32 Adjusted 900.00 ✓ 120.00 50 80.00 × 150.00 80
1 2 3 4 5 6 7 ECON No. 1 2 3 4	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NOT TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 120.00 80.00 200.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 120.00 50 80.00 X 150.00 80 30.00 ✓
1 2 3 4 5 6 7 No. 1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NOT TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO N	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction PLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 Repairer 1,100.00 80.00 200.00 30.00 80.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 32 Adjusted 900.00 \square 120.00 50 80.00 X 150.00 80 30.00 \square 80.00 30
1 2 3 4 5 6 7 7 ECON No. 1 2 3 4 5 6 7	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEMOVE/INSTALL EXHAUST SILENCER ASSEMBLY	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction PLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 30 Adjusted 900.00 ✓ 120.00 50 80.00 × 150.00 80 30.00 ✓ 80.00 × 120.00 30 120.00 ×
1 2 3 4 5 6 7 ECON 1 2 3 4 5 6 7 8	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MIMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEW TO REMOVE/INSTALL EXHAUST SILENCER ASSEMBLY RUST PROOFING ON THE REAR ACCIDENT AFFECTED.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction PLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE. O TO REPAIR.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00 60.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 32 Adjusted 900.00 \$\frac{1}{2}\$ 80.00 \$\frac{3}{2}\$ 60.00 30
1 2 3 4 5 6 7 8 8 8 8 9 1 2 3 4 5 6 7 7 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEW TO REMOVE/INSTALL EXHAUST SILENCER ASSEMBLY RUST PROOFING ON THE REAR ACCIDENT AFFECTED.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction PLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE. O TO REPAIR.		100.00 100.00 100.00 150.00 80.00 100.00 450.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00	60.00 30 80.00 15 80.00 × nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 30 Adjusted 900.00 ✓ 120.00 50 80.00 × 150.00 80 30.00 ✓ 80.00 × 120.00 30 120.00 ×
1 2 3 4 5 6 7 ECON 1 2 3 4 5 6 7 8	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MIMENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEW TO REMOVE/INSTALL EXHAUST SILENCER ASSEMBLY RUST PROOFING ON THE REAR ACCIDENT AFFECTED.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE. Y TO REPAIR. O PORTIONS. LID, REAR END PANEL	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00 60.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 120.00 50 80.00 X 150.00 80 30.00 ✓ 80.00 X 60.00 30 600.00 ✓
1 2 3 4 5 6 7 ECON No. 1 2 3 4 5 6 7 8	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEW TO REMOVE/INSTALL EXHAUST SILENCER ASSEMBLY RUST PROOFING ON THE REAR ACCIDENT AFFECTED.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction PLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE. O TO REPAIR.	_	100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00 60.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 32 Adjusted 900.00 \$\frac{1}{2}\$ 80.00 \$\frac{3}{2}\$ 60.00 30
1 2 3 4 5 6 7 FECON 1 2 3 4 5 6 6 7 8	TRUNK LID INNER SEALER TRUNK LID INTERIOR TRIM LINING CLIPS TRUNK COMPARTMENT SIDE TRIM LINING CLIPS REAR END PANEL JOINT SEALANT REAR END PANEL INNER GARNISH CLIPS REAR BUMPER CLIPS REAR BUMPER PARKING SENSORS MENDED LABOUR TO CUT/WELD REAR END PANEL TO RENEW AND REDAMAGED PARTS. TO TRANSFER TAILGATE LOCKING MECHANISM AND TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TAILGATE. TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TO REMOVE/INSTALL TRUNK COMPARTMENT TRIM FACILITATE THE REPAIR. TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRIN TO INSTALL REAR BUMPER PARKING SENSORS TO NEW TO REMOVE/INSTALL EXHAUST SILENCER ASSEMBLY RUST PROOFING ON THE REAR ACCIDENT AFFECTED.	Necessary Necessary Necessary Necessary Necessary Necessary Dented/Malfunction EPLACE REAR ACCIDENT OOTHER COMPONENTS NEW TAILGATE PANEL. AND GARNISHES TO G SYSTEM. EW BUMPER FACE. Y TO REPAIR. O PORTIONS. LID, REAR END PANEL		100.00 100.00 100.00 150.00 80.00 100.00 450.00 1,080.00 Repairer 1,100.00 80.00 200.00 30.00 80.00 120.00 60.00	60.00 30 80.00 15 80.00 X nn 100.00 30 60.00 15 80.00 30 325.00 200 785.00 Adjusted 900.00 120.00 50 80.00 X 150.00 80 30.00 ✓ 80.00 X 60.00 30 600.00 ✓

RECOI	MMENDED LABOUR			
No.			Repairer	Adjusted
			2,590.00	2,140.00
COST	OF CLAIMS	Repairer	Adjusted	
1	TOTAL PARTS		6,288.45	5,860.05
2	TOTAL NETT ITEMS		1,080.00	785.00
3	LABOUR & SPRAY		2,590.00	2,140.00
		Gross Total (S\$):	9,958.45	8,785.05
		GST 7.00% (S\$):	-	_
		Total Amount (S\$):	9,958.45	8,785.05





