

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23001467/KVP3Q2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant: LEROY LEASING Policy No: DMHCSNW00009932201

Date of Loss: 13/01/2023 Nature of Claim: OD Claim No: SNM23D200400/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMT5940U**

Make & Model: SANYANG LA18W1-6, 172cc (A)

Engine No: 67391002095451

Reg. Date: 03/07/2020 (Man. Year: 2020)

Chassis No: KPT30A1USLP319613

Colour: Metallic Dark Blue

Odometer: 0 km

Engine Capacity: 1597 cc

Market Value/New Car Price: S\$95,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Kumho 3 mm

Rear Left Side: Kumho 3 mm

Front Right Side: Kumho 3 mm

Rear Right Side: Kumho 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,025.00	25,010.00	9,015.00	26.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,185.80	743.40	442.40	37.31
Paintwork Labour	407.56	387.94	19.62	4.81
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,618.36	26,141.34	9,477.02	26.61
- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
(S\$)	34,368.36	24,891.34	9,477.02	27.57
+ GST 8.00/8.00% (S\$)	2,749.47	1,991.31	758.16	27.57
Nett Amount (S\$)	37,117.83	26,882.65	10,235.18	27.57

INSPECTION

Date of Assignment: 10/02/2023 Present Location:

Ding Auto Pte Ltd (HQ)

Date Inspected: 22/02/2023 Inspected At:

Ding Auto Pte Ltd (HQ)

176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jul 2023)	
Parts:	N/A	SANYANG LA18W1-6 172cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT5940U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS - TOTAL AMOUNT		31,950.00 F	*22,935.00 F
Supplementary #1						
2	1		*CROSSMEMBER BEAM LH	Bent	390.00 F	*390.00 F
3	1		*BRAKE HOSE FRONT LH	Punctured	170.00 F	*170.00 F
4	1		*ABS SENSOR FRONT LH	Shorted	295.00 F	*295.00 F
5	1		*GRILLE - CENTRE	Cracked	320.00 F	*320.00 F
6	1		*GRILLE ASSY - INTAKE	Cracked	250.00 F	*250.00 F
7	1		*FRONT LOWER BUMPER	Cracked	650.00 F	*650.00 F
F=Franchise part.						
Total Parts (S\$)					34,025.00	25,010.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	256.20	239.40
2	Total Paint Materials	New	151.36	148.54
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	1,185.80	743.40
Gross Labour Cost (S\$)			1,593.36	1,131.34

Report was unsubmitted during this print-out.

< END OF ESTIMATES >