

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI23001468/RQY3E2**Date:** 12/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMA6527Z**Insured Vehicle No :** GBJ2661C

Date of Loss: 10/01/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMA6527Z**

Make &amp; Model: NISSAN QASHQAI, 1.2 DIG-T CVT (A)

Engine No: HRA2567826A

Reg. Date: 14/06/2018 (Man. Year: 2018)

Chassis No: SJNFEAJ11U2236262

Colour: White

Odometer: 106642 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,062.15	3,587.07	1,475.08	29.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	730.00	880.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,672.15</b>	<b>4,317.07</b>	<b>2,355.08</b>	<b>35.30</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,672.15</b>	<b>3,450.00</b>	<b>3,222.15</b>	<b>48.29</b>

INSPECTION

Date of Assignment: 10/02/2023

Date Inspected: 13/02/2023 Inspected At:

Kok Wang Car Grooming (HQ)  
1 SOON LEE STREET #06-40 PIONEER CENTRE  
Singapore 627605

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2023)
<b>Parts:</b>	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA6527Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	737.50 FL	*717.00 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	25.90 FL	*- FL
3	1		*FRONT BUMPER FINISHER RH	Scratched	119.30 FL	*119.30 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	118.80 FL	*- FL
5	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
6	1		*FRONT FENDER ARCH GARNISH RH	Scratched	584.20 FL	*266.00 FL
7	1		*FRONT HEADLAMP RH	Scratched	3,496.80 FL	*2,850.00 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
9	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	278.40 FS	*- FS
10	1		*FRONT BUMPER FOG LAMP BRACKET RH	Not Necessary	149.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,570.40</b>	<b>3,982.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	508.25	395.23
<b>Total Parts (\$\$)</b>	<b>5,062.15</b>	<b>3,587.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE & PANEL BEATING AFFECTED PORTION	New	800.00	300.00
2	TO SPRAY PAINT ON AFFECTED PORTION	New	700.00	400.00
3	TO APPLY ANTI-RUST ON AFFECTED AREAS	New	60.00	0.00
4	TO CHECK WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,610.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >