

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001470/AQP3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00239232202		
Claimant Vehicle No :	SMU2147H	Insured Vehicle No :	SMN8309E		
Date of Loss:	08/02/2023	Nature of Claim:	TP	Claim No:	SNM23D201038/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU2147H		Engine No:	G4LCKU243304
Make & Model:	HYUNDAI ACCENT (RB), 1.4 CVT (A)		Chassis No:	KMHCU41BTKU481352
Reg. Date:	01/08/2020 (Man. Year: 2019)		Odometer:	45705 km
Colour:	Blue			
Engine Capacity:	1368 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	2,354.08	1,155.04	1,199.04	50.93	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,050.00	480.00	570.00	54.29	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	3,404.08	1,635.04	1,769.04	51.97	
Approved Total (Overridden) (S\$)		1,300.00			
	(S\$)	3,404.08	1,300.00	2,104.08	61.81
	+ GST 8.00/8.00% (S\$)	272.33	104.00	168.33	61.81
	Nett Amount (S\$)	3,676.41	1,404.00	2,272.41	61.81

INSPECTION

Date of Assignment:	10/02/2023		
Date Inspected:	03/04/2023	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts: 143	HYUNDAI ACCENT (RB) 1.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU2147H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	545.30 FL	*545.30 FL
2	2		*REAR BUMPER SIDE HOLDER -LH & RH	Not Necessary	71.20 FL	*- FL
3	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	191.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Deformed	390.80 FL	*390.80 FL
5	5		*REAR BUMPER BRACKET	Not Necessary	90.00 FL	*- FL
6	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	740.40 FL	*370.20 FL
7	4		*REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
8	2		*TAILLAMP -LH & RH	Not Necessary	776.40 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,935.10	1,436.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	581.02	281.26
Total Parts (\$\$)	2,354.08	1,155.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS	New	400.00	200.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	500.00	200.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
			Gross Labour Cost (\$\$)	1,050.00
				480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >