



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 3723H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSY	WARPED	950.00	651.20
1	REAR BUMPER ASSY UPPER LH	WARPED	250.00	180.20
1	REAR BUMPER RETAINER LH	CRACKED	120.00	47.00
1	REAR TAILGATE MIRROR	SERVICEABLE	300.00	-
1	REAR FENDER ASSY LH	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR TAILLAMP ASSY LH	CRACKED	450.00	368.10
1	REAR END PANEL LH	TO REPAIR SEE LABOUR	980.00	-
	LESS 25% DISCOUNT		-1,212.50	-311.62
			3,637.50	934.88
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	SET REAR BUMPER SENSOR (SN)	MALFUNCTION	350.00	200.00
			450.00	230.00
<u>LABOUR</u>				
	TO CUT, WELD, STRAIGHTEN, AFFECTED AREAS AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER ASSY LH AND REAR END PANEL LH. }		1,800.00	600.00
	TO REMOVE AND INSTALL REAR BUMPER ASSY. }		180.00	-
	TO REMOVE AND INSTALL REAR TAILLAMP ASSY. }		180.00	-
	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS. JOB ALLOWANCE.		1,800.00	600.00
	TO CHECK REAR LIGHTING AND WIRING.		150.00	30.00
	TO REMOVE AND INSTALL REAR GARNISH AND TRIM TO FACILITATE THE REPAIR.		280.00	60.00
	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS.		300.00	30.00
	TO REMOVE AND INSTALL REAR TAILGATE MIRROR.	NOT NECESSARY	180.00	-
	TO REMOVE AND INSTALL REAR BUMPER SENSOR.		180.00	30.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	300.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK CENTRAL DOOR LOCK SYSTEM.	NOT NECESSARY	150.00	-
			5,500.00	1,350.00
GRAND TOTAL			9,587.50	2,514.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS3/CTI22009985/Twy3m4-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.