

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23001494/KVY3Q2**Date:** 23/05/2023REFERENCE

Insured/Claimant: QUEK PEI JIN (GUO PEIJIN) Policy No: SP2002711186-01
Date of Loss: 06/02/2023 Nature of Claim: OD Claim No: 202332005158

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG6440X**
Make & Model: HONDA VEZEL, 1.5 G CVT (A) Engine No: L15Z1003938
Reg. Date: 24/08/2022 (Man. Year: 2021) Chassis No: RV31003188
Colour: Metallic Grey Odometer: 14865 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$126,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,096.52	6,543.80	6,552.72	50.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,260.00	1,640.00	56.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,996.52	7,803.80	8,192.72	51.22
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	14,896.52	6,703.80	8,192.72	55.00
+ GST 8.00/8.00% (S\$)	1,191.72	536.30	655.42	55.00
Nett Amount (S\$)	16,088.24	7,240.10	8,848.14	55.00

INSPECTION

Date of Assignment: 10/02/2023
Date Inspected: 13/02/2023 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts: 144	HONDA VEZEL 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNG6440X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,520.10 FL	*1,520.10 FL
2	2		*BONNET RUBBER -LH/RH	Serviceable	156.00 FL	*- FL
3	1		*BONNET RUBBER -INNER	Serviceable	96.00 FL	*- FL
4	1		*BONNET LOCK	Repair	237.00 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	253.00 FL	*- FL
6	2		*BONNET HINGE-LH/RH	Repair	196.00 FL	*- FL
7	1		*SUPPORT PANEL TOP GARNISH	Serviceable	384.00 FL	*- FL
8	1		*SUPPORT PANEL ASSY	Repair	868.00 FL	*- FL
9	1		*FRONT BUMPER -TOP	Bent	1,350.70 FL	*927.50 FL
10	1		*FRONT BUMPER-LOWER	Serviceable	367.00 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER -LH/RH	O/S Distorted	63.60 FL	*31.80 FL
12	1		*FRONT BUMPER TOWING COVER -RH	Serviceable	68.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Repair	460.50 FL	*- FL
14	1		*FRONT BUMPER FOGLAMP COVER -LH/RH	O/S Cut	186.00 FL	*93.00 FL
15	2		*FRONT BUMPER FOGLAMP -LH/RH	Serviceable	790.00 FL	*- FL
16	1		*FRONT BUMPER CENTRE LOWER GRILLE	Serviceable	256.00 FL	*- FL
17	1		*FRONT BUMPER CENTRE LOWER LIP	Buckled	395.00 FL	*381.70 FL
18	1		*FRONT FENDER O/S	Bent	785.40 FL	*580.00 FL
19	1		*FRONT FENDER OUTER ARCH GARNISH O/S	Distorted	253.00 FL	*253.00 FL
20	1		*HEADLAMP ASSY O/S	Mtg Cracked	2,150.80 FL	*2,150.80 FL
21	1		*HEADLAMP LOWER RETAINER O/S	Serviceable	102.00 FL	*- FL
22	1		*FRONT GRILLE TOP BRACKET	Repair	39.00 FL	*- FL
23	1		*FRONT GRILLE TOP GARNISH	Serviceable	87.00 FL	*- FL
24	1		*FRONT GRILLE LOGO	Serviceable	98.00 FL	*- FL
25	1		*FRONT GRILLE INNER	Serviceable	436.00 FL	*- FL
26	1		*FRONT GRILLE OUTER	Serviceable	624.00 FL	*- FL
27	2		*FRONT GRILLE TOP BRACKET -LH/RH	Repair	58.00 FL	*- FL
28	1		*FRONT FENDER COWLING O/S	Distorted	125.80 FL	*125.80 FL
29	1		*FRONT SHOCK ABSORBER O/S	Serviceable	310.70 FL	*- FL
30	1		*FRONT LOWER ARM O/S	Serviceable	398.50 FL	*- FL
31	1		*FRONT KNUCKLE O/S	Bent	335.10 FL	*335.10 FL
32	1		*FRONT KNUCKLE BEARING O/S	Necessary	168.50 FL	*168.50 FL
33	1		*FRONT REINFORCEMENT	Repair	460.50 FL	*- FL
34	8		*BONNET INSULATOR CLIP	Not Necessary	28.00 FS	*- FS
35	8		*SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	28.00 FS	*- FS
36	10		*FRONT BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
37	1		*COOLANT	Not Necessary	40.00 FS	*- FS
38	1		*FRONT NUMBER PLATE WITH FRAME	Serviceable	55.00 FS	*- FS
39	2		*GRILLE LOGO CLIP	Not Necessary	5.00 FS	*- FS
40	8		*FRONT FENDER OUTER ARCH GARNISH O/S CLIPS	Necessary	28.00 FS	*28.00 FS
41	8		*FRONT FENDER COWLING CLIPS	Necessary	28.00 FS	*28.00 FS
42	1		*FRONT ALLOY WHEEL O/S	Dented	713.60 FS	*500.00 FS
43	1		*FRONT FOG LAMP COVER RH	Dented	85.00 FL	*85.00 FL
44	1		*FRONT FOG LAMP COVER OUTER GARNISH RH	Cracked	45.50 FL	*45.50 FL
45	1		*FRONT FOG LAMP RH	Cracked	551.30 FL	*510.70 FL
46	1		*FRONT FOG LAMP INNER BRACKET RH	Cracked	27.50 FL	*27.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER SENSOR RH	Shorted	303.10 FL	*126.70 FL
48	1		*WIPER WASHER TANK	Dented	78.30 FL	*78.30 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					16,130.50	8,032.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,033.98	1,488.20
Total Parts (\$\$)					13,096.52	6,543.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTIONS .TO PANEL BEAT ,RESHAPE STRAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	500.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	600.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
5	TO REMOVE AND REPLACE O/S FRONT RIM .TO PERFORM TYRE BALANCING	New	50.00	20.00
6	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	60.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (\$\$)			2,900.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >