

Inspection Services Pte Ltd

Date

: 02 October 2019

To

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House

Singapore 189556

Attn

: Ms Juliana Lee

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No - AV21572

Company Reg No -201318067R GST Reg No - 201318067R

7 OCT 201

MOTOR

CLAIM

TAX INVOICE

YOUR REF / CLAIM NUMBER

: MT/1048939-002

OUR REF

AVS2019-20409/BL

TP VEHICLE NO

: FBA6091T

CLAIM TYPE

: PRE-REPAIR SURVEY

DATE OF SURVEY

: 22 August 2019

Description

Amount (S\$)

1

No.

Professional fee

50.00

Subtotal GST 7.00% 50.00 3.50

Total

53.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Juliana Lee

Assign Date:
Accident Date:

Place of Survey:

21/08/2019

Survey Date:

22/08/2019

00-01-00 TP Policy No:

NA

Our Ref:

AVS2019-20409/BL

Occi Sono Motor

25 Kaki Bukit Road 4, #01-38 Synergy

Your Ref:

MT/1048939-002

Singapore

417800

Claim Type:

Third Party

Description of Vehicle:

Veh. No:

FBA6091T

Make/Model:

Honda Super 4

Colour: Engine Capacity:

Blue NA Engine No: Chassis No: NA NA

Odometer:

NA

Reg. Date:

NA

Condition of Vehicle:

General:

Good

Modification:

No

Affected

Steering: Paint work: Affected

Handbrake: Tyre Make: Affected Michelin

120/60R17

Front Side:

Footbrake:

4mm

Good

Front Tyre Size: Rear Tyre Size:

120/60R17

Rear Side:

4mm

Description of Damage:

The vehicle sustained damage on the front portion.

The front headlamp, front fork, front fairing and front meter were among the items affected.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than S\$1,800.00 and could take approximately third (3) working days to complete.



COMPLETED DI OCT 2019

Adjuster:

Billy Loh Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Our Ref: AV\$2019-20409/BL Your Ref: MT/1048939-002 Pre-repair survey - 22/08/2019













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Our Ref: Your Ref: AVS2019-20409/BL MT/1048939-002

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Our Ref: Your Ref: AVS2019-20409/BL MT/1048939-002

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: AVS2019-20409/BL Your Ref: MT/1048939-002 Re-survey items - 03/09/2019













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: Your Ref: AVS2019-20409/BL

ef: MT/1048939-002

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref: Your Ref: AVS2019-20409/BL MT/1048939-002

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Your Ref: MT/1048939-002
Our Ref: AVS2019-20409/BL
Post repair survey - 26/09/2019









Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.