

**ACCIDENT DAMAGED VEHICLE INSPECTION REPORT**

M/S : Mohamed Sanip Bin Jasmawi
C/O Occi_Sono Motor.Com
25 Kaki Bukit Road 4 #01-38
(Synergy KB) Singapore 417800

Date : 30 December 2019
Our Ref : TP/OCCI/FBA6091T/8293

REFERENCE PARTICULARS

Date of Accident : 13 June 2019
Date of Inspection : 14 August 2019

Type of Inspection : Third Party Claim
Date of Re-Inspn : ~

VEHICLE PARTICULARS

Registration No : FBA 6091 T
Make : Honda
Model : CB400
Year : 2006 (COE Expiry 29/06/2026)

Engine No : NC23E3100119
Chassis No : JH2NC39986M200102
Odometer : ~
Colour : Blue

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Front brake : Affected
Rear brake : Serviceable

General Body Work : Good
Steering : Affected
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

Location	Make	Size	Thread Balance
Front	Michelin	120/60ZR17	3 mm
Rear	Michelin	160/60ZR17	4 mm

GENERAL DESCRIPTION OF DAMAGES

The motorcycle sustained damage at the front & left side portion.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **\$4,300.00 nett** at lump sum basis. (Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Five (5) working days.

Enclosed Twenty-Four (24) photographs depicting damage to the vehicle.

Inspection conducted at : Occi_Sono Motor.Com
25 Kaki Bukit Road 4 #01-38 (Synergy KB) Singapore 417800

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a **"WITHOUT PREJUDICE BASIS"**.

VEHICLE NO : FBA 6091 T
MAKE/MODEL: HONDA CB400

Our Ref : TP/OCCI/FBA6091T/8293

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION	
1	Handle bar	1	Bent	\$ 120.00	\$ 120.00	✓
2	Handle bar balancer LH	1	Grazed	\$ 20.00	\$ 20.00	✓
3	Clutch lever	1	Grazed	\$ 28.00	\$ 28.00	✓
4	View mirror LH	1 set	Grazed	\$ 120.00	\$ 120.00	✓
5	Meter assy	1	Cracked	\$ 925.00	\$ 925.00	✓
6	Headlamp assy	1	Missing	\$ 260.00	\$ 260.00	✓
7	Headlamp rim	1	Missing	\$ 68.00	\$ 68.00	✓
8	Headlamp housing	1	Cracked	\$ 75.00	\$ 75.00	✓
9	Headlamp stay	1	Bent	\$ 85.00	\$ 85.00	✓
10	Front signal lamp LH	1	Broken	\$ 65.00	\$ 65.00	✓
11	Front fender	1	Cracked	\$ 216.00	\$ 216.00	✓
12	Fork inner tubes L/R @ \$215.00	2	Bent	\$ 430.00	\$ 430.00	✓
13	Fork under bracket	1	Bent	\$ 245.00	\$ 245.00	✓
14	Front wheel rim	1	Grazed/Warped	\$ 750.00	\$ 750.00	✓ R
15	Front brake disc L/R @ \$445.00	2	LH only (Warped)	\$ 890.00	\$ 445.00	✓ H/L
16	Fuel tank	1	Dented	\$ 890.00	\$ 890.00	✓ R
17	Engine cover LH	1	Grazed	\$ 120.00	\$ 120.00	✓
18	Engine cover gasket LH	1	Necessary	\$ 8.00	\$ 8.00	✓ H/L
19	Gear shift pedal	1	Bent	\$ 68.00	\$ 68.00	✓
20	Front footrest LH	1	Grazed	\$ 55.00	\$ 55.00	✓
21	Footrest bracket LH	1	Serviceable	\$ 158.00		✓ H/L
22	Rear footrest LH	1	Grazed	\$ 28.00	\$ 28.00	✓
23	Rear cowling	1	Grazed	\$ 285.00	\$ 285.00	✓
24	Rear signal lamp LH	1	Broken	\$ 65.00	\$ 65.00	✓
				\$ 5,974.00	\$ 5,371.00	
			Less 10%	\$ 597.40	\$ 537.10	
				\$ 5,376.60	\$ 4,833.90	
B)	<u>S/NET ITEM</u>					
25	Fuel tank emblem	1 set	Necessary	\$ 58.00	\$ 58.00	✓
26	Steering upper/lower cone bearing	1 set	Necessary	\$ 60.00	\$ 60.00	✓
27	Front number plate	1	Bent	\$ 10.00	\$ 10.00	✓
28	Fork oil seal & duct cover L/R @ \$30.00	2	Necessary	\$ 60.00	\$ 60.00	✓
29	Fork oil	1	Necessary	\$ 30.00	\$ 30.00	✓
			Parts Total :	\$ 5,594.60	\$ 5,051.90	
C)	<u>LABOUR CHARGES</u>					
30	Transportation charge. (2 Trips)			\$ 80.00	\$ 80.00	✓ H/L
31	Replace, realign & adjust above damaged parts. Rim balancing, check wiring, re-connection & lighting system.			\$ 450.00	\$ 300.00	✓ 250/-
			Labour Total :	\$ 530.00	\$ 380.00	
			Total Parts and Labour	\$ 6,124.60	\$ 5,431.90	
					\$ 4,300.00	

FINAL LUMP SUM ADJUSTMENT

VEHICLE NO : FBA 6091 T
MAKE/MODEL: HONDA CB400

Our Ref : TP/OCCI/FBA6091T/8293

REMARKS

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$4,300.00 nett** corresponding to replacement of parts and labour charges. We now revert for your decision on the above claim.

Yours faithfully
KTO Automobile Assessors



Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser