



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 6091T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	120.00	120.00
1	HANDLE BAR BALANCER LH	GRAZED	20.00	20.00
1	CLUTCH LEVER	GRAZED	28.00	28.00
1	SET VIEW MIRROR LH	GRAZED	120.00	120.00
1	METER ASSY	CRACKED	925.00	925.00
1	HEADLAMP ASSY	MISSING	260.00	260.00
1	HEADLAMP RIM	MISSING	68.00	68.00
1	HEADLAMP HOUSING	CRACKED	75.00	75.00
1	HEADLAMP STAY	BENT	85.00	85.00
1	FRONT SIGNAL LAMP LH	BROKEN	65.00	65.00
1	FRONT FENDER	CRACKED	216.00	216.00
2	FORK INNER TUBES L/R @ \$215.00	BENT	430.00	430.00
1	FORK UNDER BRACKET	BENT	245.00	245.00
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	750.00	-
2	FRONT BRAKE DISC L/R @ \$445.00	NOT NECESSARY	890.00	-
1	FUEL TANK	DENTED	890.00	890.00
1	ENGINE COVER LH	GRAZED	120.00	120.00
1	ENGINE COVER GASKET LH	NOT NECESSARY	8.00	-
1	GEAR SHIFT PEDAL	BENT	68.00	68.00
1	FRONT FOOTREST LH	GRAZED	55.00	55.00
1	FOOTREST BRACKET LH	NOT NECESSARY	158.00	-
1	REAR FOOTREST LH	GRAZED	28.00	28.00
1	REAR COWLING	GRAZED	285.00	285.00
1	REAR SIGNAL LAMP LH	BROKEN	65.00	65.00
	LESS 10% DISCOUNT		-597.40	-416.80
			5,376.60	3,751.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET FUEL TANK EMBLEM (SN)	NECESSARY	58.00	58.00
1	SET STEERING UPPER/LOWER CONE BEARING (SN)	NECESSARY	60.00	60.00
1	FRONT NUMBER PLATE (SN)	BENT	10.00	10.00

Report Ref No. CS1/LAW23001498/Dny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OIL SEAL & DUET COVER L/R @ \$30.00 (SN)	NECESSARY	60.00	60.00
1	FORK OIL (SN)	NECESSARY	30.00	30.00
			218.00	218.00
	LABOUR			
	TRANSPORTATION CHARGE. (2 TRIPS).	NOT NECESSARY	80.00	-
	REPLACE, REALIGN & ADJUST ABOVE DAMAGED PARTS. RIM BALANCING, CHECK WIRING, RE-CONNECTION & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM.		450.00	250.00
			530.00	250.00
GRAND TOTAL			6,124.60	4,219.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CS1/LAW23001498/Dny3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.