

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001502/KPA3Q2**Date:** 04/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070109339
Claimant Vehicle No :	SNH3917C	Insured Vehicle No :	SMU6003M
Date of Loss:	08/02/2023	Nature of Claim:	TP
		Claim No:	5031585977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH3917C	Engine No:	HIDDEN
Make & Model:	BYD E6 (ME-2), (A)	Chassis No:	LC0CE4DCXN0267119
Reg. Date:	25/10/2022 (Man. Year: 2022)	Odometer:	27241 km
Colour:	Metallic Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	CHAO YANG 9 mm	Rear Left Side:	CHAO YANG 9 mm
Front Right Side:	CHAO YANG 9 mm	Rear Right Side:	CHAO YANG 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,195.00	2,655.00	540.00	16.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	890.00	350.00	28.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,435.00	3,545.00	890.00	20.07
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,435.00	2,800.00	1,635.00	36.87
+ GST 8.00/8.00% (S\$)	354.80	224.00	130.80	36.87
Nett Amount (S\$)	4,789.80	3,024.00	1,765.80	36.87
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,266.00		

INSPECTION

Date of Assignment:	14/02/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	14/02/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	2,950.00 FL	*2,950.00 FL
2	2		*REAR DOOR HINGE	Repair	340.00 FL	*- FL
3	1		*REAR DOOR WEATHERSTRIP	Serviceable	260.00 FL	*- FL
4	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	3,550.00 2,950.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	355.00 295.00
					Total Parts (\$\$)	3,195.00 2,655.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST RR ACCIDENT AREA	New	500.00	400.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	500.00	400.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM	New	120.00	60.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
Gross Labour Cost (S\$)			1,240.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >