



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 4972C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FORK ASSY - L/H	SERVICEABLE	1,700.00	-
1	FRONT FORK ASSY - R/H	SERVICEABLE	1,700.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	1,250.00	-
1	FRONT SPORT RIM	SERVICEABLE	1,008.00	-
2	FRONT BRAKE DISC	NOT NECESSARY	1,010.00	-
1	FRONT RIM BEARING	NOT NECESSARY	200.00	-
1	FRONT RIM SHAFT	TO REPAIR SEE LABOUR	375.00	-
1	HEADLAMP	CRACKED	2,100.00	1,100.00
1	SIDE MIRROR	DAMAGED	280.00	148.00
1	HANDLE-BAR	NOT NECESSARY	550.00	-
1	HANDLE-BAR BALANCERS N/S	CUT	200.00	60.00
1	SET HAND GRIP	NOT NECESSARY	150.00	-
1	BRAKE LEVER	CUT	158.00	120.00
1	FRONT SIGNALS N/S	CRACKED	380.00	150.00
1	FRONT FENDER	CUT	350.00	235.00
1	FRONT INNER COVER	CRACKED	850.00	420.00
2	BOARD FOOTREST - L/R/H	N/S TORN	1,050.00	405.00
1	BOARD FOOTREST LOWER COVER N/S	TORN	65.00	65.00
1	BOARD FOOTREST CENTRE LOWER COVER	DISTORTED	650.00	390.00
1	SET FAIRING	CUT / CRACKED	1,650.00	1,100.00
1	SIDE STAND	CUT	220.00	177.00
1	MAIN STAND	TO REPAIR SEE LABOUR	950.00	-
	LESS 10% DISCOUNT		-1,684.60	-437.00
			15,161.40	3,933.00
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE COVER PROTECTOR (SN)	CUT	90.00	90.00
1	REAR BOX (SN)	SERVICEABLE	380.00	-
1	REAR BOX BRACKET (SN)	SERVICEABLE	180.00	-
			894.00	90.00
	LABOUR			
	TO PROVIDE TOWING SERVICE (LOD).		50.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT RIM SHAFT AND MAIN STAND.		420.00	350.00
	TO RESPRAY PAINTING.		800.00	500.00
			1,350.00	900.00
GRAND TOTAL			17,405.40	4,923.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS1/LAW23001505/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.