



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1810L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER COVER	SCRATCHED	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	28.00	-
1	FRT WHEEL HUB CAP LH	SCRATCHED	346.40	346.40
1	FRT FENDER LH	DENTED	588.80	588.80
1	EMBLEM- BLUE DRIVE LH	NECESSARY	26.60	26.60
1	FRT DOOR MIRROR ASSY LH	TO REPAIR SEE LABOUR	1,391.70	-
1	HEADLAMP LH	SCRATCHED	2,110.30	2,110.30
1	FRT BUMPER SIDE MOULDING LH	NOT NECESSARY	93.60	-
1	DAY LIGHT RH	NOT NECESSARY	642.50	-
	LESS 20% DISCOUNT		-1,146.20	-715.04
			4,584.80	2,860.16
	<u>SPECIAL NETT ITEMS</u>			
1	RENEW ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT DOOR MIRROR ASSY LH.		1,100.00	700.00
	SPRAY PAINTING CHARGE.		900.00	500.00
	CHECK ALL LIGHTING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
			2,120.00	1,230.00
	GRAND TOTAL		6,904.80	4,290.16

Report Ref No. NS/INC23001512/Svp3m4

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,450.00
---	--	--	-----------------

Report Ref No. NS/INC23001512/Svp3m4



S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.