



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3535Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CUT	591.75	591.75
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,111.93	-
1	FRONT FENDER (HYBRID) RH	NECESSARY	86.50	86.50
	LESS 25% DISCOUNT		-453.05	-169.56
			1,359.13	508.69
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADV. STICKER RH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
			1,400.00	1,200.00
	GRAND TOTAL		2,859.13	1,808.69
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,450.00

Report Ref No. NS/INC23001513/Sqp3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.