

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23001518/Twp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	08-05-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBK 3743M	Veh. Ir	spected	SH 7343Y	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1208455-002	Exces	s (\$)	0.00	
	Assign From		Assigr	n Date	06/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVLU188640	Colou	•	BLUE	
	Odometer	567122	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	_AKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST I	_AKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	04/02/2023	Inspec	tion Date	06/02/2023	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					