

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4723E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRKT RH / LH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR SMART KEY ANTENNA	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-355.97	-94.65
			1,423.88	378.60
	NETT ITEMS			
1	REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
1	REAR NO.PLATE WITH TRIM COVER (YELLOW) (N)	BENT	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,505.38	1,058.10





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23001522/Twp3m4

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**