

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS23001528/KQY3Q2**Date:** 17/04/2023**REFERENCE**

Insured/Claimant: Mercedes-Benz Fleet Management Singapore Pte. Ltd. Policy No: SP2003907937

Date of Loss: 07/02/2023

Nature of Claim: OD

Claim No: 202332005283

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMT1227Y**  
 Make & Model: MERCEDES-BENZ CLA 200, 1.3 SB PROGRESSIVE (A) Engine No: 28291480298857  
 Reg. Date: 20/03/2020 (Man. Year: 2019) Chassis No: W1K1183872N081710  
 Colour: Metallic Pearl White Odometer: 70006 km  
 Engine Capacity: 1332 cc  
 Market Value/New Car Price: S\$163,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm  
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,157.45	2,535.50	5,621.95	68.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	580.00	2,790.00	82.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,527.45</b>	<b>3,115.50</b>	<b>8,411.95</b>	<b>72.97</b>
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	10,827.45	2,415.50	8,411.95	77.69
<b>+ GST 8.00/8.00% (S\$)</b>	866.20	193.24	672.96	77.69
<b>Nett Amount (S\$)</b>	<b>11,693.65</b>	<b>2,608.74</b>	<b>9,084.91</b>	<b>77.69</b>

**INSPECTION**

Date of Assignment: 13/02/2023

Date Inspected: 14/02/2023 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	143	MERCEDES-BENZ CLA 200 1.3 SB PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT1227Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE (WCP)	Cracked	168.00 F	*168.00 F
2	1		*FRONT GRILLE CENTRE LOGO (WCP)	Missing	115.00 F	*115.00 F
3	1		*FRONT GRILLE BEAM (WCP)	Cracked	168.00 F	*168.00 F
4	2		*FRONT GRILLE BEAM MOULDING (WCP)	Dented	116.00 F	*116.00 F
5	2		*HEADLAMP ASSY -LH/RH (WCP)	Serviceable	3,760.00 F	*- F
6	1		*FRONT BUMPER (WCP)	Buckled	950.00 F	*950.00 F
7	1		*FRONT BUMPER CENTRE LOGO (WCP)	Necessary	62.00 F	*62.00 F
8	2		*FRONT BUMPER SIDE RETAINER RH/LH (WCP)	Serviceable	48.00 F	*- F
9	1		*FRONT BUMPER LOWER GRILLE (WCP)	Serviceable	125.00 F	*- F
10	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	350.00 F	*350.00 F
11	1		*FRONT BUMPER SPONGE (WCP)	Cracked	98.00 F	*98.00 F
12	2		*FRONT BUMPER SENSOR (WCP)	Serviceable	276.00 F	*- F
13	6		*FRONT BUMPER SENSOR SEAL (WCP)	Necessary	48.00 F	*48.00 F
14	1		*FRONT RADAR SENSOR (WCP)	Serviceable	850.00 F	*- F
15	1		*FRONT NUMBER PLATE GARNISH (WCP)	Cracked	75.00 F	*75.00 F
16	1		*FRT GRILLE INNER SUPPORT (WCP)	Cracked	55.00 F	*55.00 F
17	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
18	1		*FRONT GRILLE CLIPS (6 PCS)	Necessary	36.30 FS	*20.00 FS
19	1		*FRONT BUMPER CLIPS (15 PCS)	Necessary	90.75 FS	*50.00 FS
						F=Franchise part. S=SpcNett.
					Sub Total (\$\$)	7,431.05 2,315.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	726.40 220.50
					Total Parts (\$\$)	8,157.45 2,535.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	120.00	60.00
2	TO PANEL BEAT AND STRAIGHTEN FRONT SUPPORT PANEL ,FRONT CHASSIS FRAME ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,500.00	250.00
3	TO PUTTY AND SPRAY ON THE ACCIDENT AREAS	New	1,200.00	250.00
4	TO RE-PROGRAM FRONT HEADLAMP	New	350.00	0.00
5	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
6	TO REMOVE AND REFIT RADAR SENSOR	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,370.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >