

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001536/KNP3E2**Date:** 19/06/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00014002200
Claimant Vehicle No :	SLQ2423T	Insured Vehicle No :	SNG5137D
Date of Loss:	31/01/2023	Nature of Claim: TP	Claim No: SNM23D200820/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2423T		
Make & Model:	MERCEDES-BENZ C180, 1.8 CGI (A)	Engine No:	27182030065620
Reg. Date:	28/07/2010 (Man. Year: 2010)	Chassis No:	WDD2040492A393099
Colour:	Metallic Grey	Odometer:	210385 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,660.90	2,265.00	395.90	14.88
Miscellaneous Items	200.00	0.00	200.00	100.00
Labour	1,340.00	960.00	380.00	28.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,200.90	3,225.00	975.90	23.23
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	4,200.90	2,750.00	1,450.90	34.54
+ GST 8.00/8.00% (S\$)	336.07	220.00	116.07	34.54
Nett Amount (S\$)	4,536.97	2,970.00	1,566.97	34.54

INSPECTION

Date of Assignment:	13/02/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	28/03/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	MERCEDES-BENZ C180 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2423T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	810.00 F	*810.00 F
2	1		*1 PC REAR BUMPER CENTRE MOULDING	Necessary	65.00 F	*65.00 F
3	1		*1 PC REAR BUMPER SIDE MOULDING	Necessary	62.00 F	*62.00 F
4	1		*1 PC REAR BUMPER LH SIDE RETAINER	Distorted	28.00 F	*28.00 F
5	1		*1 PC LH TAILLAMP	Cracked	365.00 F	*365.00 F
6	1		*1 PC REAR BOOT LOGO	Serviceable	28.00 F	*- F
7	1		*1 PC REAR BOOT EMBLEM (C180)	Serviceable	56.00 F	*- F
8	1		*1 PC REAR BOOT EMBLEM (CGI)	Serviceable	70.00 F	*- F
9	1		*1 PC REAR EXHAUST PIPE	Bent	935.00 F	*935.00 F

F=Franchise part.

Sub Total (S\$)	2,419.00	2,265.00
+ Margin on L,N Items 10.00/0.00% (S\$)	241.90	0.00
Total Parts (S\$)	2,660.90	2,265.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REAR BUMPER LH REVERSE SENSOR (SERVICEABLE)	200.00	0.00
Sub Total (\$)			200.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER, KNOCK & REPAIR REAR LH FENDER, BOOT AND REALIGN THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY ON REAR BUMPER, REAR LH FENDER, BOOT	New	780.00	500.00
3	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	60.00	60.00
Gross Labour Cost (\$)			1,340.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >