

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22012147/RWY3E2-1**Date:** 15/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : FBS4894L **Insured Vehicle No :** SMS2653Z
 Date of Loss: 27/11/2022 Nature of Claim: TP Claim No: MFL2022D0010675

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBS4894L**
 Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS Engine No: G3P4E0002273
 Reg. Date: 10/05/2021 (Man. Year: 2020) Chassis No: MH3SG6420LJ002273
 Colour: Black Odometer: 39527 km
 Engine Capacity: 155 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 140/70-14
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,668.87	2,289.78	2,379.09	50.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	250.00	1,070.00	81.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,988.87	2,539.78	3,449.09	57.59
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	5,988.87	2,000.00	3,988.87	66.60
+ GST 8.00/8.00% (S\$)	479.11	160.00	319.11	66.60
Nett Amount (S\$)	6,467.98	2,160.00	4,307.98	66.60

INSPECTION

Date of Assignment: 13/02/2023
 Date Inspected: 05/12/2022 Inspected At: Excel Cycle (HQ)
 48 TOH GUAN ROAD EAST #01-112
 Singapore 608586
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Mar 2023)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS4894L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UPPER HANDLEBAR COVER	Serviceable	160.00 FL	*- FL
2	1		*HANDLEBAR COMPLETE	Bent	120.00 FL	*120.00 FL
3	1		*SET HANDLEBAR BALANCER (END GRIPS)	Cut / Missing	60.00 FL	*60.00 FL
4	1		*SET WIND MIRROR	O/S Cut	130.00 FL	*130.00 FL
5	1		*FRONT CENTRE PANEL	Cut	155.00 FL	*155.00 FL
6	1		*BODY COWLING LH / RH	N/S Cut/ O/S NotNecessary	235.00 FL	*117.50 FL
7	1		*HEADLAMP ASSY (LED)	Scratched	685.00 FL	*685.00 FL
8	2		*FRONT SIGNAL	Serviceable	172.00 FL	*- FL
9	2		*FRONT FORK ASSY	Not Necessary	825.40 FL	*- FL
10	1		*FRONT FORK UNDER BRACKET	Not Necessary	217.40 FL	*- FL
11	1		*FRONT FENDER	Cut	110.00 FL	*110.00 FL
12	1		*FENDER INNER PANEL	Cracked	115.80 FL	*115.80 FL
13	1		*UPPER LED SHIELD COVER ASSY	Cracked	142.50 FL	*142.50 FL
14	1		*LED SHIELDS INNER PANEL LH	Hdr Cracked	215.00 FL	*215.00 FL
15	1		*FOOT BOARD	N/S Cracked/O/SNotNecessary	325.60 FL	*81.40 FL
16	1		*FOOTREST BOARD LOWER SIDE COVER	N/S Cut/ O/S NotNecessary	257.20 FL	*128.60 FL
17	1		*AIR BOX COVER	Grazed	138.40 FL	*138.40 FL
18	1		*SET STEERING CONE BEARING	Not Necessary	180.00 FS	*- FS
19	1		*SET BODY STICKER	Necessary	180.00 FS	*120.00 FS
20	1		*REAR BOX	Cracked	350.00 FS	*150.00 FS
21	1		*SET REAR BOX RACK WITH BASE	Not Necessary	220.00 FS	*- FS
22	1		*BRAKE LEVER	N/S Bent/ O/S NotNecessary	90.00 FL	*45.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,084.30	2,514.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	415.43	224.42
Total Parts (\$\$)	4,668.87	2,289.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (2 TRIPS)	New	150.00	0.00
2	FRONT CASH WHEEL BALANCE	New	120.00	20.00
3	CHASSIS FRAMES ALIGN	New	550.00	80.00
4	WORKMANSHIP	New	500.00	150.00
Gross Labour Cost (\$\$)			1,320.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >