

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 10.02.2023

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO : SNC3511R
MODEL : TOYOTA NOAH HYBRID
DATE OF ACCIDENT : 10.02.2023
TIME OF ACCIDENT : 23:35 HOURS

Xiao Teng

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 1,339.31	\$ 1,339.31 <i>1085</i>
2	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 28.10	\$ 28.10 <i>+</i>
3	REAR BUMPER REFLECTOR <i>RH could</i>	2	\$ 125.60	\$ 251.20 <i>125.60</i>
4	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 145.80	\$ 291.60 <i>+</i>
5	TAILGATE <i>Rehd</i>	1	\$ 1,812.70	\$ 1,812.70 <i>+</i>
6	TAIL GATE LOGO <i>new</i>	1	\$ 78.00	\$ 78.00 <i>+</i>
7	TAIL GATE EMBLEM 'HYBRID SYNERGY DRIVE' <i>new</i>	1	\$ 75.20	\$ 75.20 <i>+</i>
8	TAILGATE STOPPER <i>2</i>	2	\$ 28.60	\$ 57.20 <i>+</i>
9	TAILGATE INNER LOCK	1	\$ 452.10	\$ 452.10 <i>+</i>
10	TAILGATE LOWER LOCK	1	\$ 36.70	\$ 36.70 <i>+</i>
11	TAILGATE INNER TRIM	1	\$ 580.30	\$ 580.30 <i>+</i>
12	TAILGATE INNER HOLDER	1	\$ 65.00	\$ 65.00 <i>+</i>
13	TAILGATE WEATHER STRIP	1	\$ 375.10	\$ 375.10 <i>+</i>
14	TAILGATE WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,198.70	\$ 1,198.70 <i>+</i>
15	TAIL LAMP <i>new</i>	2	\$ 853.30	\$ 1,706.60 <i>+</i>
16	TAIL LAMP LOWER GARNISH <i>RH ton</i>	2	\$ 178.80	\$ 357.60 <i>178.80</i>
17	TAIL LAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 160.70	\$ 321.40 <i>+</i>
18	REAR FENDER INNER TRIM <i>23MP</i>	2	\$ 906.51	\$ 1,813.02 <i>+</i>
19	REAR FENDER COWLING <i>new</i>	2	\$ 118.70	\$ 237.40 <i>+</i>
20	REAR END PANEL C/W END EXTEND PANEL <i>new</i>	1	\$ 762.20	\$ 762.20 <i>+</i>
21	REAR END PANEL TOP GARNISH <i>Rehd</i>	1	\$ 168.20	\$ 168.20 <i>+</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNC3511R**
 MODEL : **TOYOTA NOAH HYBRID**
 DATE OF ACCIDENT : 10.02.2023
 TIME OF ACCIDENT : 23:35 HOURS

22	REAR FLOOR PANEL TOP BOARD <i>cracked</i>	1	\$ 1,165.50	\$ <u>1,165.50</u> <i>691</i>
23	JACK COVER GARNISH <i>Not in</i>	1	\$ 186.00	\$ 186.00 <i>x.</i>

3086
2314.50

TOTAL PRICE \$ 13,359.13
 LESS 25% \$ 3,339.78
SUB TOTAL PRICE \$ 10,019.35

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 80.00	\$ 80.00 <i>x.</i>
2	REAR BUMPER CLIPS (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00 <i>30-</i>
3	TAIL LAMP CLIP (SET) <i>Not in</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
4	TAIL LAMP LOWER GARNISH CLIP (SET) <i>Not in</i>	1	\$ 60.00	\$ 60.00 <i>10</i>
5	TAILGATE OUTER MOULDING CLIP (SET) <i>?</i>	1	\$ 40.00	\$ 40.00 <i>x</i>
6	TAILGATE INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00 <i>x</i>
7	TAILGATE TOP INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00 <i>x</i>
8	TAILGATE SIDE INNER TRIM CLIP (SET) <i>Not in</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
9	TAILGATE WINDSCREEN SEALANT <i>Not in</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
10	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00 <i>x</i>
11	TAILGATE WINDSCREEN SOLAR FILM	1	\$ 550.00	\$ 550.00 <i>x</i>
12	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00 <i>x</i>
13	REAR FENDER INNER COWLING CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00 <i>x.</i>
14	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Not in</i>	1	\$ 40.00	\$ 40.00 <i>10.</i>
15	REAR END PANEL INSULATION SEAL <i>Not in</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
16	REVERSE CAMERA <i>Not in</i>	1	\$ 450.00	\$ 450.00 <i>x</i>
17	REVERSE SENSOR (2PCS) <i>Not in</i>	1	\$ 250.00	\$ 250.00 <i>200</i>

310

TOTAL \$ 2,240.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>700</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNC3511R**
 MODEL : **TOYOTA NOAH HYBRID**
 DATE OF ACCIDENT : 10.02.2023
 TIME OF ACCIDENT : 23:35 HOURS

3	TUFF COAT	\$ 250.00	80
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	50
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	X
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X.
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	X
9	TRANSFER TAILGATE MECHANISM	\$ 120.00	X
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,190.00

TOTAL PARTS COST : \$ 12,259.35
 TOTAL LABOUR COST : \$ 5,190.00
 TOTAL REPAIR COST : \$ 17,449.35

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
 1/s 21/02/23

050 days

total: 4114.50

L/s: 3.3K

3.3K

1490