

RECEIVED: [Signature]

REF: CS/UIS 23001607/Tuy 3.

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated cost: \_\_\_\_\_  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop no: \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: 1bn  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SML 2878D Yr Regn: 2019, May  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Honda Shuttle c.c. 1496  
Colour: white A/C: Insured / Std / Nil / NA  
Sp. Reading: 55341 T/Radio: Insured / Std / Nil / NA  
Eng/No: \_\_\_\_\_  
C/No: GK8 200239E  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: Q92K  
IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seat: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
Turn Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Tyre Size: F: 205/50R16  
R: ^ ^  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PR / SUNI /  
TOYO / YDIO, DT  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.L. 14/2/23  
Survey held at KFS  
Des. of Damages: F / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action/Instruction

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_  
Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
S + RS \_\_\_\_\_  
Partic \_\_\_\_\_



# 簡福星嘍王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001738454	Date of Loss:	08/02/2023
Vehicle Reg. No.:	SML878D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AW JIA QUAN ARRON		

Make/Model:	HONDA SHUTTLE, 1.5 (A)	Vehicle Reg. Date:	13/05/2019
Vehicle Colour:	METALLIC PEARL WHITE		
Engine No:	L15B6002806	Chassis No:	GK82002392
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: KAN FOOK SING MOTOR WORKSHOP (DEFU)

### COST OF CLAIMS

	Amount
Parts	11,073.70
Miscellaneous Items	115.00
Labour	1,230.00
Paintwork Labour	850.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>13,268.70</b>
<b>+ GST 8.00% (S\$)</b>	<b>1,061.50</b>
<b>Nett Amount (S\$)</b>	<b>14,330.20</b>

This claim is handled by: MT TAN

# REPAIR DETAILS

## Reference

**Part Source:** (Last Synchronised: 13 Feb 2023)  
**Parts:** N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Kan Fook Sing Motor Workshop/SML878D/13/02/2023 17:54  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS	0.00	0.00	<i>cur</i> *700.00 F
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	<i>new</i> *55.00 F
3	1		*ROOF GARNISH LH	0.00	0.00	? *85.00 F
4	1		*FRONT WIPER GARNISH	0.00	0.00	? *140.00 F
5	1		*FRONT BONNET	0.00	0.00	<i>bt</i> *450.00 F
6	1		*FRONT BONNET HINGE RH	0.00	0.00	<i>bt</i> *22.00 F
7	1		*FRONT BONNET HINGE LH	0.00	0.00	<i>bt</i> *22.00 F
8	1		*FRONT BONNET LOCK	0.00	0.00	? *75.00 F
9	1		*FRONT BONNET INSULATOR	0.00	0.00	<i>de</i> *85.00 F
10	10		*FRONT BONNET INSULATOR CLIP	0.00	0.00	<i>new</i> *25.00 F
11	1		*FRONT BONNET CABLE	0.00	0.00	? *35.00 F
12	1		*FRONT BONNET RUBBER	0.00	0.00	? *18.00 F
13	1		*FRONT GRILLE BASE	0.00	0.00	<i>new</i> *140.00 F
14	1		*FRONT GRILLE CHROME TOP	0.00	0.00	<i>cur</i> *180.00 F
15	1		*FRONT GRILLE CHROME LOWER	0.00	0.00	<i>cur</i> *90.00 F
16	1		*FRONT GRILLE EMBLEM	0.00	0.00	<i>new</i> *15.00 F
17	1		*FRONT GRILLE TOP GARNISH	0.00	0.00	? *40.00 F
18	8		*FRONT GRILLE TOP GARNISH CLIP	0.00	0.00	? *20.00 F
19	1		*FRONT HEADLAMP RH	0.00	0.00	? *1,400.00 F
20	1		*FRONT HEADLAMP LH	0.00	0.00	<i>cur</i> *1,400.00 F
21	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	? *30.00 F
22	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	<i>dis</i> *30.00 F
23	1		*FRONT BUMPER	0.00	0.00	<i>de</i> *450.00 F
24	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *200.00 F
25	1		*FRONT BUMPER CENTRE GRILLE	0.00	0.00	? *35.00 F
26	1		*FRONT BUMPER SDIE RETAINER RH	0.00	0.00	? *10.00 F
27	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	<i>dis</i> *10.00 F
28	10		*FRONT BUMPER CLIP	0.00	0.00	<i>new</i> *25.00 F
29	1		*FRONT SUPPORT PANEL	0.00	0.00	? *1,000.00 F
30	1		*AIR CON CONDENSER	0.00	0.00	? *550.00 F
31	1		*AIR CON DISCHARGE HOSE	0.00	0.00	? *130.00 F
32	1		*AIR CON SUCTION HOSE	0.00	0.00	? *110.00 F
33	1		*AIR CON LIQUID PIPE	0.00	0.00	? *95.00 F
34	1		*AIR CONFAN ASSY	0.00	0.00	? *275.00 F
35	1		*RADIATOR	0.00	0.00	? *520.00 F
36	1		*RAIDATOR TOP BRACKET RH	0.00	0.00	? *20.00 F
37	1		*RADIATOR TOP BRACKET LH	0.00	0.00	? *20.00 F
38	1		*RADIATOR TOP HOSE	0.00	0.00	? *20.00 F
39	1		*RADIATOR SPARE TANK	0.00	0.00	? *25.00 F
40	1		*RADIATOR FAN ASSY	0.00	0.00	? *220.00 F
41	1		*AIR CLEANER OUTER DUCT	0.00	0.00	? *35.00 F
42	1		*AIR CLEANER BOX	0.00	0.00	? *70.00 F
43	1		*BATTERY TRAY	0.00	0.00	? *65.00 F
44	1		*MANIFOLD INTAKE	0.00	0.00	? *280.00 F
45	1		*ENGINE TOP COVER	0.00	0.00	? *185.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT FENDER RH	0.00	0.00	bt *130.00 F
47	1		*FRONT FENDER LH	0.00	0.00	bt *130.00 F
48	1		*FRONT FENDER SHIELD RH	0.00	0.00	x *85.00 F
49	1		*FRONT FENDER SHIELD LH	0.00	0.00	x *85.00 F
50	1		*FRONT FENDER INENR DUCT RH	0.00	0.00	? *45.00 F
51	1		*FRONT FENDER INNER DUCT LH	0.00	0.00	? *45.00 F
52	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	? *50.00 F
53	1		*FRONT FENDER TOP BRACKET RH	0.00	0.00	? *45.00 F
54	1		*FRONT FENDER TOP BRACKET LH	0.00	0.00	? *45.00 F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>10,067.00</b>
+ Margin on L,N Items 10.00% (S\$)	1,006.70
<b>Total Parts (S\$)</b>	<b>11,073.70</b>

Kan Fook Sing Motor Workshop/SML878D/13/02/2023 17:54. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	ERP STICKER	15.00
2	1	FRONT NUMBER PLATE	50.00
3	1	FRONT WINDSCREEN GUM	50.00
<b>Sub Total (S\$)</b>			<b>115.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	SPRAYPAINTING CHARGES	New 750	850.00
<b>Labour Items</b>			
2	TO CHECK WIRING SYSTEM	New 30	60.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New ?	100.00
4	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New ✓	120.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New 700	950.00
<b>Gross Labour Cost (S\$)</b>			<b>2,080.00</b>

Kan Fook Sing Motor Workshop/SML878D/13/02/2023 17:54. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfkin 97495749  
Not Authorised  
Ex: tba  
14/2/23 @ 11:50pm  
tanfkin@khaunt.com  
7 days  
P/P - Resurvey before paint

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: