



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBV 1010A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED/TORN	1,616.00	1,616.00
1	REAR BUMPER LOWER GARNISH	CRACKED	116.45	116.45
1	REAR BUMPER REINFORCEMENT	BENT	811.45	811.45
1	REAR BUMPER INNER TOP RETAINER	CRACKED	182.30	182.30
1	REAR BUMPER INNER CENTRE GARNISH	CRACKED	168.42	168.42
2	REAR BUMPER PDC SENSORS @\$363.00	MALFUNCTION	726.00	726.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	820.00	-
	LESS 10% DISCOUNT		-449.06	-367.06
			4,041.56	3,303.56
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		800.00	480.00
			1,820.00	1,090.00
GRAND TOTAL			5,861.56	4,393.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/TP23001609/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.