

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 8240X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)	DEFORMED	733.90	720.60
1	REAR BUMPER CENTER BRACKET (N)	BENT	141.30	141.30
1	TAILGATE (N)	DENTED	1,816.70	1,816.70
1	LOGO (N)	NOT NECESSARY	94.00	-
1	NV350 LOGO (N)	NOT NECESSARY	94.00	-
1	URVAN LOGO (N)	NOT NECESSARY	94.00	-
1	TAILGATE LOCK (N)	NOT NECESSARY	287.10	-
1	REAR END PANEL (N)	NOT NECESSARY	187.10	-
1	REAR END SPONGE RH (NPA) (N)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-344.81	-267.86
			3,103.29	2,410.74
	SPECIAL NETT ITEMS			
2	SEALANT @ \$20 EA (SN)	NECESSARY	40.00	40.00
1	70 KM STICKER (SN)	NECESSARY	10.00	10.00
1	8 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			260.00	260.00
	<u>LABOUR</u>			
	TO REPAIR,REPLACE TAILGATE, REAR END PANEL,REAR BUMPER, BRACKET AND AFFECTED AREA.		1,200.00	500.00
	TO PUTTY AND RESPRAY TAILGATE, REAR END PANEL,REAR BUMPER, BRACKET AND AFFECTED AREA.		1,000.00	600.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		150.00	120.00
	TO INSTALL REVERSE SENSOR AND WIRING.		120.00	40.00
	TO APPLY TUFF KOTE.		50.00	30.00
	TO REMOVE AND REFIT UPHOLSTERY TO ASSIST WORK.	NOT NECESSARY	200.00	-
	TO TRANSFER OLD TAILGATE MECHANISM TO NEW TAILGATE.		150.00	60.00
			2,870.00	1,350.00
	GRAND TOTAL		6,233.29	4,020.74

Report Ref No. CS/LIP23001613/Uvy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 4,020.74

Report Ref No. CS/LIP23001613/Uvy3m4

* NO SECOND HAND PARTS
MARKET VALUE: \$33,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,999.00=NETT VALUE: \$21,001.00

CHUA KANG SENG

Licensed Appraiser