

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS23001617/KNY3Q2**Date:** 15/05/2023**REFERENCE**

Insured/Claimant: Mercedes-Benz Fleet Management Singapore Pte Ltd Policy No: SP2003907937

Date of Loss: 26/01/2023

Nature of Claim: OD

Claim No: 202332004936

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN8972B**
 Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091031239675
 Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: WDD1760422J584823
 Colour: Metallic Grey Odometer: 114861 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: S\$73,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
 Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,803.80	3,017.20	786.60	20.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,190.00	1,440.00	54.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,433.80	4,207.20	2,226.60	34.61
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	5,733.80	3,507.20	2,226.60	38.83
+ GST 8.00/8.00% (S\$)	458.70	280.58	178.12	38.83
Nett Amount (S\$)	6,192.50	3,787.78	2,404.72	38.83

INSPECTION

Date of Assignment: 14/02/2023

Date Inspected: 14/02/2023 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	144	MERCEDES-BENZ A180 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8972B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY LH (WCP)	Cut	620.00 F	*620.00 F
2	1		*FRONT FENDER LH (WCP)	Bent	490.00 F	*490.00 F
3	1		*FRONT FENDER INNER SHIELD LH (WCP)	Serviceable	168.00 F	*- F
4	1		*FRONT BUMPER (WCP)	Buckled	780.00 F	*780.00 F
5	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Distorted	24.00 F	*24.00 F
6	1		*FRONT BUMPER SENSOR LH (WCP)	Serviceable	138.00 F	*- F
7	6		*FRONT BUMPER SENSOR SEALS (WCP)	Necessary	48.00 F	*48.00 F
8	1		*FRONT SPORT RIM LH (WCP)	Dented	690.00 F	*690.00 F
9	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
10	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*FRONT TYRE LH	Serviceable	450.00 FS	*- FS
					Sub Total (\$\$)	3,508.00 2,752.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	295.80 265.20
					Total Parts (\$\$)	3,803.80 3,017.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN FRONT SUPPORT PANEL ,LH FRONT FENDER INNER PANEL ,LH FRONT CHASSIS FRAME ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	400.00
5	TO RESET AND REPROGRAM HEADLAMP FAULT CODE	New	350.00	250.00
6	TO COMPUTERISE CHECK WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			2,630.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >