

ASS. REC. BY:

REF:

A15/23 001 617/kny3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.1% %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLN 8972 B

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mc A180

c.c

1595

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

114861

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD1760422J384823

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/01/2023

ESTIMATE

NO : QUOT202302-000026(00)

DATE : 07/02/2023

POLICY NO : SP2003907937

VEH REG NO : SLN8972B

MAKE/MODEL : MERCEDES BENZ A180 FL
STYLE (R17 HLG)

CHASSIS NO : WDD1760422J584823

ENGINE NO : 27091031239675

REG. DATE : 2017

Not Authorized
Running Repair
4 days
Ex TRA

Estimate Repair Cost to Vehicle No : SLN8972B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy LH	1	620.00	620.00 ✓
2 Front fender LH	1	490.00	490.00 ✓
3 Front fender inner shield LH	1	168.00	168.00 X
4 Front bumper	1	780.00	780.00 ✓
5 Front bumper side retainer LH	1	24.00	24.00 ✓
6 Front bumper sensor LH	1	138.00	138.00 X
7 Front bumper sensor seals	6	8.00	48.00 ✓
8 Front sport rim LH	1	690.00	690.00 ✓
			2,958.00
		Add 10%	295.80
			3,253.80
SPECIAL NET			
9 Front tyre LH	1	450.00	450.00 X
			450.00
LABOUR			
10 To remove and refit front bumper sensor	1	100.00	100.00 60%
11 To check and rectify wiring system	1	80.00	80.00 20%
12 To panel beat and straighten front support panel, LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 400%
13 To putty and spray paint on the affected areas	1	1,000.00	1,000.00 400%
14 To reset and reprogram headlamp fault code	1	350.00	350.00 250%
			2,530.00
			5,783.80
		TOTAL	S\$ 6,233.80
		ADD GST @ 8%	498.70
		GRAND TOTAL	S\$ 6,732.50

SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED THIRTY-TWO AND CENTS FIFTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD