

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001619/UNP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00226172202

**Claimant Vehicle No :** SNB3102T **Insured Vehicle No :** SLR6152T

Date of Loss: 12/02/2023 Nature of Claim: TP Claim No: SNM23D201116/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNB3102T**

Make & Model: KIA NIRO HYBRID, 1.6 (A) Engine No: G4LEHS244502

Reg. Date: 07/12/2017 (Man. Year: 2017) Chassis No: KNACC81CVJ5114527

Colour: Blue Odometer: 79693 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,800.58	757.35	5,043.23	86.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	770.00	2,470.00	76.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,040.58</b>	<b>1,527.35</b>	<b>7,513.23</b>	<b>83.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,040.58</b>	<b>1,200.00</b>	<b>7,840.58</b>	<b>86.73</b>

**INSPECTION**

Date of Assignment: 13/02/2023

Date Inspected: 14/02/2023 Inspected At: BARTLEY BIZ CENTRE

Estimated Period of Repair: 3.0 days Repairer: Zoom Autowerks Pte Ltd (Bedok)

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2023)
Parts:	M1-SUV	KIA NIRO HYBRID 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB3102T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	1,289.00 FL	*- FL
2	1		*REAR TAILGATE LOCK	Not Necessary	58.50 FL	*- FL
3	1		*REAR TAILGATE LOGO	Not Necessary	48.50 FL	*- FL
4	1		*REAR TAILGATE RUBBER	Not Necessary	232.60 FL	*- FL
5	1		*REAR END PANEL	Repair	696.50 FL	*- FL
6	1		*REAR END PANEL INNER GARNISH	Not Necessary	142.60 FL	*- FL
7	1		*REAR BUMPER	Deformed / Torn	741.50 FL	*741.50 FL
8	1		*REAR BUMPER INNER SPONGE	Not Necessary	145.00 FL	*- FL
9	1		*REAR BUMPER LOWER GRILLE	Repair	525.00 FL	*- FL
10	2		*REAR BUMPER REFLECTORS	Not Necessary	216.00 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	325.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	66.00 FL	*- FL
13	2		*REAR BUMPER SIDE MOULDINGS	Not Necessary	470.00 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
15	1		*REAR BUMPER LOWER SPOILER	Not Necessary	750.00 FS	*- FS
16	1		*REAR NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
17	1		*SET REAR REVERSE SENSOR	Serviceable	480.00 FS	*- FS
					Sub Total (S\$)	6,296.20 831.50
					- List Item Discount on L Items 10.00/10.00% (S\$)	495.62 74.15
					Total Parts (S\$)	5,800.58 757.35

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPLACE DAMAGED LAMPS & CHECK UP WIRING	New	80.00	20.00
2	TO REMOVE & REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE & REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO APPLY UNDERCOATING	New	150.00	0.00
6	PANEL BEATING	New	1,400.00	300.00
7	TO RE-SPRAY THE AFFECTED AREAS	New	1,200.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>3,240.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >