



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4241D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	55.80	-
1	HEAD LAMP RH	CRACKED	2,110.30	2,110.30
1	FRONT GRILLE CENTRE MOULDING	TO REPAIR SEE LABOUR	368.50	-
1	FRONT BUMPER GRILLE RH	SCRATCHED	186.90	186.90
1	FRONT DAY RUNNING LIGHT RH	SCRATCHED	642.50	642.50
1	FRONT BUMPER	CRACKED	481.10	481.10
1	FRONT FENDER EMBLEM RH	NECESSARY	26.60	26.60
1	FRONT FENDER RH	DENTED	588.80	588.80
	LESS 20% DISCOUNT		-892.10	-807.24
			3,568.40	3,228.96
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT RH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT GRILLE CENTRE MOUDLING.		800.00	700.00
	SPRAY PAINTING.		800.00	500.00
	CHECK LIGHTING.		60.00	30.00
	TOWING FEE.		60.00	60.00
			1,720.00	1,290.00
	GRAND TOTAL		5,388.40	4,618.96

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	-----------------

Report Ref No. CS/SMR23001620/Sny3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.