

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001631/RVP3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW0046052201
Claimant Vehicle No :	SJL8679H	Insured Vehicle No :	SMJ5526K
Date of Loss:	01/02/2023	Nature of Claim:	TP
		Claim No:	SNM23D200919/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL8679H	Engine No:	L15A71800847
Make & Model:	HONDA CITY, 1.5 LX (A)	Chassis No:	MRHGM26709P020174
Reg. Date:	15/12/2008 (Man. Year: 2008)	Odometer:	199414 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,856.48	1,011.44	845.04	45.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	880.00	1,580.00	64.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,316.48	1,891.44	2,425.04	56.18
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	4,316.48	1,500.00	2,816.48	65.25

INSPECTION

Date of Assignment:	14/02/2023		
Date Inspected:	15/02/2023	Inspected At:	1 SOON LEE STREET #06-40 Repairer:Kok Wang Car Grooming (HQ)
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	143	HONDA CITY 1.5 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL8679H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	463.70 FL	*463.70 FL
2	2		*REAR BUMPER RETAINER LH & RH	Not Necessary	43.00 FL	*- FL
3	2		*REAR BUMPER BRACKET LH & RH	Not Necessary	29.60 FL	*- FL
4	1		*REAR END PANEL	Not Necessary	399.30 FL	*- FL
5	1		*REAR END PANEL GARNISH	Not Necessary	109.40 FL	*- FL
6	1		*REAR BOOTLID	Bent	535.40 FL	*535.40 FL
7	1		*REAR BOOTLID LOGO EMBLEM	Necessary	17.80 FL	*17.80 FL
8	1		*REAR BOOTLID CITY EMBLEM	Necessary	16.20 FL	*16.20 FL
9	1		*REAR BOOTLID IVTEC EMBLEM	Necessary	22.00 FL	*22.00 FL
10	1		*REAR BOOTLID LOCK	Cut	97.30 FL	*97.30 FL
11	1		*REAR BOOTLID WEATHERSTRIP	Necessary	74.40 FL	*74.40 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
13	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
14	1		*SET REVERSE SENSOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,218.10	1,256.80
- List Item Discount on L Items 20.00/20.00% (S\$)	361.62	245.36
Total Parts (S\$)	1,856.48	1,011.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REPLACE & PANEL BEATING AFFECTED PORTION	New	1,000.00	400.00
2	TO SPRAY PAINT ON AFFECTED PORTION	New	1,000.00	400.00
3	TO REMOVE/REPLACE /REINSTALL REAR PANEL UPHOLSTERY & TRIM	New	200.00	0.00
4	TO APPLY ANTI-RUST ON AFFECTED AREAS	New	100.00	40.00
5	TO REMOVE/REFIT REVERSE SENSOR	New	100.00	40.00
6	TO CHECK WIRING FOR REAR PORTION	New	60.00	0.00
Gross Labour Cost (\$\$)			2,460.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >