

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23001632/TQY3Q2**Date:** 25/07/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

SMX2596D

Insured Vehicle No :

SLE9665D

Date of Loss: 12/02/2023

Nature of Claim:

TP

Claim No:

DMPC2300097H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMX2596D**

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR2G72808

Reg. Date: 02/01/2021 (Man. Year: 2020)

Chassis No: ZVW516144028

Colour: Black

Odometer: 54885 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,600.50	638.00	962.50	60.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,890.00	1,260.00	630.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,490.50	1,898.00	1,592.50	45.62
+ GST 8.00/8.00% (S\$)	279.24	151.84	127.40	45.62
Nett Amount (S\$)	3,769.74	2,049.84	1,719.90	45.62

INSPECTION

Date of Assignment: 14/02/2023 Present Location:

Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)

Date Inspected: 21/02/2023 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX2596D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH (WCP)	Bent	580.00 F	*580.00 F
2	1		*FRT DOOR OUTER HANDLE RH (WCP)	Not Necessary	130.00 F	*- F
3	1		*FRT DOOR OUTER HANDLE ASSY RH (WCP)	Not Necessary	120.00 F	*- F
4	1		*FRT DOOR LOCK (WCP)	Not Necessary	220.00 F	*- F
5	1		*FRT DOOR GLASS OUTER MOULDING RH (WCP)	Not Necessary	50.00 F	*- F
6	1		*FRT DOOR GLASS REGULATOR RH (WCP)	Not Necessary	85.00 F	*- F
7	1		*FRT DOOR GLASS MOTOR RH (WCP)	Not Necessary	270.00 F	*- F
						F=Franchise part.
					Sub Total (\$)	1,455.00 580.00
					+ Margin on L,N Items 10.00/10.00% (\$)	145.50 58.00
					Total Parts (\$)	1,600.50 638.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK RR DOOR RH,ROCKER PANEL RH,WELD ,REMOVE & REPLACE ABOVE PARTS	New	800.00	600.00
2	TO SPRAY RR DOOR RH ,FRT DOOR RH,ROCKER PANEL RH,PUTTY AND SPRAY PAINTING ON AFFECTEDS AREAS	New	850.00	600.00
3	TO CHECK WIRING	New	30.00	0.00
4	TO TRANSFER FRT DOOR GLASS RH COMPONENT	New	60.00	60.00
5	TO SETTING AND RESET	New	150.00	0.00
Gross Labour Cost (\$\$)			1,890.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >