

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543, Email: mirage119@gmail.com

# **ACCIDENT VEHICLE INSPECTION REPORT**

Report no Vehicle no : <u>60M0223.ZAW</u> : SKK4175P

1 REFERENCE

Date of inspection

: 13 February 2023

Requested by

: Isyrafz Mcqueen

Blk 495B Tampines Street 43

#07-392

Singapore 521495

Type of survey

: Independent

Repairer

: Zoom AutoWerks Pte Ltd

130 Bedok Reservoir Road, #08-1339, Singapore 470130

Date of accident

: 5 February 2023

2 VEHICLE DATA

Make/model

: VOLKSWAGEN JETTA 1.4 TSI AT 1622G5

Chassis no

: WVWZZZ16ZDM084060

Engine no

: CAXD42596

Date of registration

: 11 July 2013

COE Expiry Date:

29 February 2028

Engine capacity

: 1390 cc

Colour

: Black

# **3 STATIC CONDITION CHECK**

Steering

: Affected

Foot brakes

: Serviceable

Hand brakes

: Serviceable

Paintwork

: Good

General Condition

: Good

#### 4 TIRE CONDITION CHECK

RH/MAKE

LH/MAKE

SIZE

Front tread

: 7 mm/Michelin

7 mm/Michelin

225/40ZR18

Rear tread

: 7 mm/Michelin

7 mm/Michelin

225/40ZR18

#### 5 BRIEF DESCRIPTION OF DAMAGE

Rear bumper dented/buckled/cut, rear bumper reinforcement dented/bent, LH taillamp scraped, rear boot lid bent, rear boot lid LH side reflector lamp scraped, front bumper dislodged/missing, LH & RH front fender dented/buckled/distorted, front LH ^& RH chassis frames bent/scraped, front suspension parts damaged, front bonnet bent/edge scraped, RH front door edge scraped, etc. Please see para. 8 of this report for more details.

## 6 **REMARKS**

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs

\$16,800.00 (lump sum)

Estimated no of days

Fifteen (15)

Submit d/5 \$ 11,600

# **8 ASSESSMENT OF DAMAGE AND COSTS**

Report no:

60M0223.ZAW

Vehicle no:

SKK4175P

SPARE PARTS		Assessed			epairer's	Revised
<u>Description</u>	Qty		Λ		<u>Amount</u>	<u>Amount</u>
Rear bumper	1	dented/buckled/cut	n		2,780.00	2,780.00
Rear bumper side reflector lamp LH	1	to reuse	11		198.00	0.00
Rear bumper side retainer LH/RH	2	necessary	11	,	196.00	196.00
Rear bumper retaining clip	10	necessary	nu	50	108.00	108.00
Rear bumper reinforcement	1	dented/bent	sur	390	680.00	680.00-
Rear lamp assy LH	1	scraped	sun	580	870.00	870.00_
Rear boot lid	1	to repair	11		3,200.00	0.00 .
Rear boot lid Volkswagen logo	1	necessary	11		190.00	190.00
Rear boot lid side reflector lamp assy LH	1	scraped	SUN.		360.00	360.00
Front bumper	1	dislodged/missing	MI	1615	2,970.00	2,970.00
Front bumper centre sponge	1	cracked	Torn	140	205.00	205.00
Front bumper side sponge LH/RH	2	cracked/squashed	7011		196.00	196.00
Front bumper side retainer LH/RH	2	broken	300		160.00	160.00
Front bumper retaining clip	10	missing	mis	S	120.00	120.00
Front wiper washer tank assy	1	squashed	de		170.00	170.00
Front number plate moulding	1	dislodged/missing	MIS		78.00	78.00
Front bumper centre grille	1	dislodged/missing	MIS		210.00	210.00
Front bumper side vent grille	2	dislodged/missing	MUS		340.00	340.00
Radiator grille	1	logo support tabs bro	ken 3n	0 60i	970.00	970.00
Radiator grille Volkswagen logo	1	dislodged/missing	MI	s lug	180.00	180.00
Front bonnet	1	to repair	1		2,770.00	0.00
LH front fender	1	buckled/distorted	Bu	L	£00.086	₩. <b>\$</b> 680.00
LH front fender splash shield	1	squashed/distorted/to	orn 70	116	290.00	290.00
LH front fender splash shield clip	8	necessary	1	u s	96.00	96.00
RH front fender	1	dented/buckled/disto		el	680.00	Yo. \$680.00.
RH front fender splash shield	1	dislodged/missing	10	1	290.00 /	61 290.00
RH front fender splash shield clip	8	missing	ne	5	96.00	96.00
RH/LH front fender front support panel	2	bent/distorted	Se	1/	90.00	90.00-
LH headlamp assy	1	leg broken	mth 0	ng 1650	1,990.00	1,990.00
RH headalmp assy	1	broken/casing cracke	d an	1600	1,990.00	1,990.00
RH front door assy	1	to repair	1		1,385.00	0.00
RH front suspension lower arm	1	bent	Su	1	582.00	582.00
LH front suspension lower arm	1	bent	Si	M	582.00	582.00
RH stabiliser bar link	1	bent	31	nf_	46.00	46.00
		Subtotal of the above			25,748.00	18,195.00
		Discount	10%/	10%	2,574.80	1,819.50
(Special Nett Item)		Subtotal 1:			23,173.20	16,375.50
Rear bumper diffuser	1	broken	Br		1,150.00	1,150.00
LH front sport rim	1	dented/scraped	1	99	950.00	950.00
RH front sport rim	1	edge dented/bent	/	2	950.00	950.00
Front number plate c/frame set	1	dislodged/missing	M	- (	70.00	70.00
		Subtotal 2:		> -	3,120.00	3,120.00
		Total cost of parts:			23,173.20	16,375.50
LABOUR						
To check wiring.					60.00	45.00
To apply anti-rust undercoat.					150.00	90.00

Report no:

60M0223.ZAW

Vehicle no:

SKK4175P

	Total cost of repair:	28,683.20	20,930.50
	Total cost of labour:	5,510.00	4,555.00
Towing fee.		120.00	120.00 /
To realign wheels by 4-wheel compute	90.00	90.00 /	
To remove and replace the damaged LH & RH front suspension parts.		500.00	400.0024
Spray painting charges to paint the at RH door, front bumper, front LH fend rear boot lid, etc.	2,000.00	1,750.00 l 400	
Labour charges to remove and rep beating affected and damaged parts. the affected front chassis frames.	2,500.00	2,000.00 Ev	
To align headlamp and refocus headla	mp beams.	90.00	60.00 20

# 9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$20,930.50

(a) The recommended cost of repair based on lump sum repairs would be

\$16,800.00

(b) The estimated number of days for the repairs would be

(1st Re-inspection conducted on 17 February 2023)

(2<sup>nd</sup> Inspection conducted on 22 February 2023)

(Post-Repair inspection conducted on 28 February 2023)

Fifteen (15)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

## Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:

Liaw Leong San

Licensed Automotive Appraiser

Dated:

11 April 2023