

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23001641/RVP3Q2**Date:** 19/06/2023**REFERENCE**

|                              |   |                             |                        |
|------------------------------|---|-----------------------------|------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00126192200     |
| <b>Claimant Vehicle No :</b> | SJM7089L                                      | <b>Insured Vehicle No :</b> | GBC4265L               |
| Date of Loss:                | 03/02/2023                                    | Nature of Claim:            | TP                     |
|                              |   | Claim No:                   | SNM23D201115/C02/TAYHP |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SJM7089L</b>                   | Engine No:  | 2AZF194729   |
| Make & Model:               | TOYOTA ESTIMA, 2.4 (A)            | Chassis No: | ACR500076903 |
| Reg. Date:                  | 14/01/2009 (Man. Year: 2008)      | Odometer:   | 234506 km    |
| Colour:                     | White                             |             |              |
| Engine Capacity:            | 2362 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/55 R17    | Rear Tyre Size:  | 215/55 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 3,475.70          | 2,311.12          | 1,164.58          | 33.51         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,300.00          | 1,260.00          | 1,040.00          | 45.22         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>5,775.70</b>   | <b>3,571.12</b>   | <b>2,204.58</b>   | <b>38.17</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>2,850.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>5,775.70</b>   | <b>2,850.00</b>   | <b>2,925.70</b>   | <b>50.66</b>  |

**INSPECTION**

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 25/04/2023 |               |  |
| Date Inspected:             | 15/02/2023 | Inspected At: | Xinya Auto Services Pte Ltd (HQ)<br>Blk 1002, #01-75, Bukit Merah Lane 3<br>Singapore 159719 |
| Estimated Period of Repair: | 4.0 days   |               |  |

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |   |
|---------------|--|---|
| Reference     |  |   |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 19 Jun 2023)           |
| Parts:        | M1-MPV   | TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                       |
| Print Code:   | (Unsubmitted, no print-code for SJM7089L)  |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

Recommended Parts

| No.  | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount                                       |
|--|-----|----------|-------------------------------|---------------|-------------|--|
| 1  | 1   |          | *REAR BUMPER                  | Cracked       | 899.50 FL   | *899.50 FL                                   |
| 2  | 1   |          | *REAR BUMPER RETAINER         | Not Necessary | 86.95 FL    | *- FL  |
| 3  | 1   |          | *TOW HOOK COVER               | Not Necessary | 36.90 FL    | *- FL  |
| 4  | 1   |          | *REAR BUMPER REFLECTOR        | Not Necessary | 69.55 FL    | *- FL  |
| 5  | 1   |          | *REAR END PANEL               | Not Necessary | 755.90 FL   | *- FL  |
| 6  | 1   |          | *REAR BUMPER BRACKET          | Not Necessary | 86.50 FL    | *- FL  |
| 7  | 1   |          | *REAR TAIL GATE               | Bent          | 1,753.80 FL | *1,753.80 FL                                 |
| 8  | 1   |          | *REAR TAIL GATE LOCK          | Not Necessary | 490.30 FL   | *- FL  |
| 9  | 1   |          | *REAR TAIL GATE WEATHERSTRIPE | Necessary     | 372.20 FL   | *372.20 FL                                   |
| 10   | 1   |          | *WINDSCREEN SEALANT           | Necessary     | 50.00 FS    | *30.00 FS                                    |
| 11   | 1   |          | *WINDSCREEN CLIPS             | Necessary     | 12.00 FS    | *12.00 FS                                    |
|  |     |          |                               |               |             | F=Franchise part. S=SpcNett. L=ListItemDisc. |
| Sub Total (S\$)                                    |     |          |                               |               | 4,613.60    | 3,067.50                                     |
| - List Item Discount on L Items 25.00/25.00% (S\$) |     |          |                               |               | 1,137.90    | 756.38                                       |
| Total Parts (S\$)                                  |     |          |                               |               | 3,475.70    | 2,311.12                                     |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | TO REMOVE & REPLACE REAR BUMPER ,TAILGATE AND TO PANEL BEAT CUT & WELD END PANEL | New      | 1,000.00        | 500.00          |
| 2                               | TO PUTTY & SPRAY PAINT REAR BUMPER TAILGATE AND OTHER AFFECTED AREA              | New      | 880.00          | 600.00          |
| 3                               | TO CHECK & RECTIFY WIRING  | New      | 60.00           | 0.00            |
| 4                               | TO REMOVE & REPLACE REAR WINDSCREEN GLASS CHECK FOR WATER TIGHT                  | New      | 180.00          | 120.00          |
| 5                               | TUFF KOTE  | New      | 180.00          | 40.00           |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>2,300.00</b> | <b>1,260.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >