

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

**INVOICE** 

Invoice No.:

CL/210544

Zulkifli Yahya

C/o: H L Cycle Pte Ltd No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

Ref No.:

HLC/11/2101/TP

Date:

18 November 2021

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
SURVEY INSPECTION FOR VEHICLE NO.	
RESURVEY INSPECTION	
DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)	
• TRANSPORTATION	
CRAND FORMA	
GRAND TOTAL	S\$ 684.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

### VEHICLE INSPECTION REPORT

To: Zulkifli Yahya

C/o: H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

Accident Date

: 30 September 2021

Inspection Date Repairer Name

: 03 November 2021

: H L Cycle Pte Ltd

No.1 Kaki Bukit Ave 6

#02-58/60 AutoBay, Singapore 417883

PARTICULARS OF VEHICLE

Registration No

: FBK 401 U

Year / Capacity:

Type of Survey: Third Party

2015 / 399 cc

: 18 November 2021

: HLC/11/2101/TP

Make / Model

: Honda CB400

Colour

Chassis No

: JH2NC4791EK000164

Mileage

Date

Our ref

White 93755

Engine No

: NC47E5000166

**CONDITION OF TYRES** 

Make

Size

Thread Balance

Rim

Front

Pirelli

120/70 -17

5 mm

Sport

5 mm

Rear

Pirelli

160/60 - 17

Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front and o/s portion. (Details refer to the photographs attached)

Enclosed number of photographs:

114

copies

#### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

#### **RECOMMENDATIONS**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$9,100.00 on a contractual basis.

Under normal circumstances, the repair period would be about 9 (Nine) working days.

## CL APPRAISER PTE LTD

Vehicle Registration No.: FBK 401 U

Our Ref No.:

HLC/11/2101/TP

Qty	Description	Conditions		Repairer's Estimate		Revised Amount
	SPARE PARTS - LIST ITEMS					
1	Front cowling	Damage	\$	196.00	\$	196.00 🗸
2	Front side cowlings	Damage	\$	770.00	\$	770.00 ✓
1	Windshield	Damage	\$	385.00	\$	385.00 ✓
1	Headlamp	Damage	\$	1,650.00	\$	1,650.00 565
1	Headlamp cover	Damage	\$	165.00	\$	165.00 ✓
1	Headlamp rear bracket	Damage	\$	85.00	\$	85.00× nn
2	Front fork assy	Damage	\$	1,900.00	\$	1,900.00 1800
1	Fork under bracket	Damage	\$	445.00	\$	445.00 ✓
1	Fork upper bracket	Damage	\$	428.00	\$	428,00 ✓
1	Front rim shaft	Necessary	\$	68.00	\$	68.00 ✓
1	Front sport rim	Damage	\$	1,350.00	\$	1,350.00 850 🗸
1	Handle bar	Damage	\$	214.00	\$	214.00 🗸
2	Handle bar ends	Damage	\$	60.00	\$	60.00 ✓
1	Side mirror	Damage	\$	95.00	\$	95.00 ✓
1	Clutch lever	Damage	\$	58.00	\$	58.00 ✓
1	Brake lever	Damage	\$	65.00	\$	65.00 ✓
2	Front signals	O/S Damage		352.00	\$	176.00 95 🗸
	Front o/s footrest	Damage	\$	75.00	\$	75.00
1	Front o/s footrest bracket	Damage	\$	245.00	\$	245.00 × nn
1	Brake pedal	Damage	\$	98.00	\$	98.00 ✓
1	Rear o/s footrest	Damage	\$	70.00	\$	70.00 <b>✓</b>
1	Rear o/s footrest bracket	Damage	\$	155.00	\$	155.00 × NN
	O/s side board	Damage	\$	130.00	\$	$130.00 \times \text{nn}$
1 (	O/s lower cowling	Damage	\$	185.00	\$	185.00 × nn
	Exhaust pipe	Damage	\$	1,600.00	\$	1,600.00 1200
	Exhaust pipe protector	Damage	\$	85.00	\$	
	Rear o/s signal	Damage		176.00	\$	85.00 ✓ 176.00 × nn
		Dulliage -	<u>\$</u>	11,105.00	\$ \$	10,929.00
		Less 10%	\$	1,110.50	\$	1,092.90
	Total Cost - List Items	2000 1070	<del>φ</del> \$	9,994.50	<u>φ</u>	9,836.10

7787 -10% 7008.30

### C L APPRAISER PTE LTD

Vehicle Registration No.: FBK 401 U

Our Ref No.:

HLC/11/2101/TP

Qty	Description	Conditions		Repairer's Estimate		Revised Amount	
	List Items Total c/f		\$	9,994.50	\$	9,836.10	
	SPECIAL NETT ITEMS						
1	Number plate (1 set)	Damage	\$	28.00	\$	28.00 20	
2	Fork oils	Necessary	\$	30.00		30.00 ✓	
2	Fork oil seals	Necessary	\$	56.00	\$	56.00 ✓	
1	Steering cone (1 set)	Necessary	\$	80.00	\$	80,00 60	
1	Rear box	Damage	\$	350.00	\$	350.00 300	
1	Rear box bracket	Damage	\$		\$	150.00 × ni	
1	Crash bar (1 set)	Damage	\$		\$	380.00 ✓	
	<b>Total Cost - Special Nett items</b>		\$	1,074.00	\$	1,074.00	

846

Total cost of parts

\$ 11,068.50	\$ 10,910.10

# C L APPRAISER PTE LTD

**GRAND TOTAL** 

Vehicle Registration No.: FBK 401 U

Our Ref No.:

\$

HLC/11/2101/TP

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	11,068.50	\$	10,910.10	
	<u>LABOUR</u>					
1	To provide towing service.	\$	50.00	\$	50.00 ✓	
2	To check electrical system, wire harness and focus headlamp.	\$	80.00	\$	50.00 30 v	
3	To provide labour charges, workmanship to dismantle above damaged parts; re-align body structure and damaged consistent to the accident.	\$	480.00	\$	400.00 300	
					380	

11,678.50 \$ 11,410.10 4 days 8234.30 L/S - 6587.44 = 6600

Vehicle Registration No.: FBK 401 U

Our Ref No.:

HLC/11/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 9,100.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

#### <u>Disclaimer</u>

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser