



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 401U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT COWLING	DAMAGED	196.00	196.00
2	FRONT SIDE COWLINGS	DAMAGED	770.00	770.00
1	WINDSHIELD	DAMAGED	385.00	385.00
1	HEADLAMP	DAMAGED	1,650.00	565.00
1	HEADLAMP COVER	DAMAGED	165.00	165.00
1	HEADLAMP REAR BRACKET	NOT NECESSARY	85.00	-
2	FRONT FORK ASSY	DAMAGED	1,900.00	1,800.00
1	FORK UNDER BRACKET	DAMAGED	445.00	445.00
1	FORK UPPER BRACKET	DAMAGED	428.00	428.00
1	FRONT RIM SHAFT	NECESSARY	68.00	68.00
1	FRONT SPORT RIM	DAMAGED	1,350.00	850.00
1	HANDLE BAR	DAMAGED	214.00	214.00
2	HANDLE BAR ENDS	DAMAGED	60.00	60.00
1	SIDE MIRROR	DAMAGED	95.00	95.00
1	CLUTCH LEVER	DAMAGED	58.00	58.00
1	BRAKE LEVER	DAMAGED	65.00	65.00
2	FRONT SIGNALS	O/S DAMAGED	352.00	95.00
1	FRONT O/S FOOTREST	DAMAGED	75.00	75.00
1	FRONT O/S FOOTREST BRACKET	NOT NECESSARY	245.00	-
1	BRAKE PEDAL	DAMAGED	98.00	98.00
1	REAR O/S FOOTREST	DAMAGED	70.00	70.00
1	REAR O/S FOOTREST BRACKET	NOT NECESSARY	155.00	-
1	O/S SIDE BOARD	NOT NECESSARY	130.00	-
1	O/S LOWER COWLING	NOT NECESSARY	185.00	-
1	EXHAUST PIPE	DAMAGED	1,600.00	1,200.00
1	EXHAUST PIPE PROTECTOR	DAMAGED	85.00	85.00
1	REAR O/S SIGNAL	NOT NECESSARY	176.00	-
	LESS 10% DISCOUNT		-1,110.50	-778.70
			9,994.50	7,008.30

Report Ref No. CS3/CTI21011210/Tnp3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	DAMAGED	28.00	20.00
2	FORK OILS (SN)	NECESSARY	30.00	30.00
2	FORK OIL SEALS (SN)	NECESSARY	56.00	56.00
1	SET STEERING CONE (SN)	NECESSARY	80.00	60.00
1	REAR BOX (SN)	DAMAGED	350.00	300.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	150.00	-
1	SET CRASH BAR (SN)	DAMAGED	380.00	380.00
			1,074.00	846.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING SERVICE.		50.00	50.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	300.00
			610.00	380.00
<b>GRAND TOTAL</b>			<b>11,678.50</b>	<b>8,234.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,600.00</b>

Report Ref No. CS3/CTI21011210/Tnp3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.