

08/11/13 wef

ASS. REC. BY: Marcus

REF:

CC6/A1423001656/423

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SNA 7528C

at Workshop m/s

Zoom

of

Insured:

G3J 845H

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

£150k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

£19A

Vehicle: IN / OUT

Date:

Person Contacted:

LYA 56334

Veh No:

SNA 7528C

Yr Regn:

02/09/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

mazda

CX-9

c.c

2488

Colour

blue

A/C:

Insured / Std / NI / NA

Sp. Reading

6255-1

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6TC 2WLA KO 3/2239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255-150 R 20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/02/23

D.O.I.

14/2/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/2/23

by 1391.98

27/2/23 4/5 @ 3600 in hand & in

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

22 February 2023

not Authorised

14/2/23

4 days. 2/5 & 3600

REG NO. : SNA 7528 C

MAKE/MODEL : MAZDA CX-9

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$S)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 225.00 ✓
1	Rear tailgate	\$ 1,771.40 ✓
1	Rear tailgate inner board	\$ 447.94 X
1	Rear tailgate outer garnish	\$ 585.56 X
1	Rear tailgate lock	\$ 197.11 X
1	Rear tailgate rubber	\$ 199.70 X
1	Rear tailgate "SKYACTIV" emblem	\$ 124.81 ✓
1	Rear tailgate "CX-9" emblem	\$ 142.47 ✓
1	Rear end panel	\$ 866.15 X
1	Rear end panel inner garnish	\$ 216.52 X
1	Rear bumper	\$ 983.48 ✓
1	Rear bumper inner sponge	\$ 236.54 X
2	Rear bumper reflectors	\$ 295.10 X
1	Rear bumper reinforcement	\$ 439.35 X
2	Rear bumper side brackets	\$ 202.54 X
2	Rear bumper side retainers	\$ 178.80 X
4	Rear bumper PDC sensors	\$ 1,420.00 2200
1	Rear bumper chrome moulding	\$ 323.00 ✓
		\$ 8,855.47
		\$ 885.55
		\$ 7,969.92
<u>SPECIAL NETT ITEMS</u>		
1	Rear windscreen sealant	\$ 80.00 40
1	Rear bumper clip (1 set)	\$ 80.00 50
		\$ 160.00

S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 X
3	To remove and refit rear reverse sensor.	\$ 180.00 50
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 80.00 60
5	To remove and refit rear windscreen glass.	\$ 180.00 120
6	To apply undercoating.	\$ 200.00 30
7	Panel beating.	\$ 1,600.00 400
8	To re-spray painting on the affected areas.	\$ 1,500.00 600
		\$ 4,000.00

GRAND TOTAL :

\$ 12,129.92