



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7041Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	500.10	500.10
1	REAR BUMPER REINFORCEMENT	BUCKLED	295.00	295.00
1	REAR BUMPER RH REFLECTOR	MTG CRACKED	40.80	40.80
1	REAR BUMPER LOWER SKIRT	BENT	262.60	262.60
6	REAR BUMPER CLIPS @\$3.80	NECESSARY	22.80	22.80
1	REAR BOOT EMBLEM	NECESSARY	28.80	28.80
	LESS 20% DISCOUNT		-230.02	-230.02
			920.08	920.08
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
	<b><u>LABOUR</u></b>			
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TO KNOCK & REPAIR REAR PANEL, BOOT & REALIGN THE SAME.		600.00	450.00
	PUTTY & RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER.		700.00	600.00
			1,300.00	1,050.00
	<b>GRAND TOTAL</b>		<b>2,420.08</b>	<b>2,170.08</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,700.00</b>

Report Ref No. CS/SPF23001663/Kqy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,700-\$1,800**

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.