



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SLH 6444D

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRONT BUMPER	TO REPAIR SEE LABOUR	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	-
1	FRONT GRILLE TOP GARNISH	TO REPAIR SEE LABOUR	-
			-
	<u>LABOUR</u>		
	SPRAY PAINTING OF DAMAGED PARTS.		400.00
			400.00
GRAND TOTAL			400.00

RECOMMENDED COST OF REPAIRS	400.00
------------------------------------	---------------

Report Ref No. CS3/SPF23001664/Dwy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$400.00-\$500.00

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.