

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23001669/HWY3E2**Date:** 13/03/2023**REFERENCE**

Insured/Claimant:	TRILLIUM LEASING PTE LTD	Policy No:	SP2002589079
Date of Loss:	14/02/2023	Nature of Claim:	OD
		Claim No:	202332005329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3344Y	Engine No:	1ZRY343115
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104561394
Reg. Date:	19/04/2017 (Man. Year: 2016)	Odometer:	237554 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goform 5 mm	Rear Left Side:	Goform 5 mm
Front Right Side:	Goform 5 mm	Rear Right Side:	Goform 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,492.00	9,647.00	-1,155.00	-13.60
Miscellaneous Items	260.00	95.00	165.00	63.46
Labour	3,040.00	2,340.00	700.00	23.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,792.00	12,082.00	-290.00	-2.46
Approved Total (Overridden) (S\$)		8,400.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	11,792.00	6,400.00	5,392.00	45.73
+ GST 8.00/8.00% (S\$)	943.36	512.00	431.36	45.73
Nett Amount (S\$)	12,735.36	6,912.00	5,823.36	45.73

INSPECTION

Date of Assignment:	14/02/2023	Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	14/02/2023	Inspected At:	Ding Auto Pte Ltd (HQ)
			176 Sin Ming Drive #04-06, Sin Ming Autocare
			Singapore 575721
Estimated Period of Repair:	6.0 days		

Adjuster: Edward**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3344Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Buckled	235.00 F	*235.00 F
2	1		*FRT BUMPER RETAINER RH	Cracked	35.00 F	*35.00 F
3	1		*FRT BUMPER RETAINER LH	Cracked	35.00 F	*35.00 F
4	1		*FRT BUMPER REINFORCEMENT	Distorted	165.00 F	*165.00 F
5	1		*FRT BUMPER FOAM	Cracked	60.00 F	*60.00 F
6	1		*FRT BUMPER CTR GRILLE	No such part	75.00 F	*- F
7	1		*FRT BUMPER UPPER GRILLE	Cracked	200.00 F	*200.00 F
8	1		*FRT BUMPER LOWER GRILLE	Dented	105.00 F	*105.00 F
9	1		*FRT BUMPER SIDE COVER RH	Dislodged	75.00 F	*75.00 F
10	1		*FRT BUMPER SIDE COVER LH	Dislodged	75.00 F	*75.00 F
11	1		*BONNET	Buckled	385.00 F	*385.00 F
12	1		*BONNET FRT SEAL	Not Necessary	45.00 F	*- F
13	1		*BONNET HINGE RH	Bent	50.00 F	*50.00 F
14	1		*BONNET HINGE LH	Bent	50.00 F	*50.00 F
15	1		*BONNET INSULATOR	Torn	195.00 F	*195.00 F
16	1		*BONNET LOCK	Bent	90.00 F	*90.00 F
17	1		*FRT SUPPORT PANEL COMPLETE	Distorted	395.00 F	*395.00 F
18	1		*FRT SUPPORT PANEL UPPER GARNISH	Not Necessary	80.00 F	*- F
19	1		*WIPER COWL PANEL	Dented	280.00 F	*280.00 F
20	1		*FRT FENDER RH	Buckled	270.00 F	*270.00 F
21	1		*FRT FENDER LH	Bent	270.00 F	*270.00 F
22	1		*FRT FENDER BRACKET RH	Not Necessary	45.00 F	*- F
23	1		*FRT FENDER BRACKET LH	Not Necessary	45.00 F	*- F
24	1		*FRT FENDER INNER COVER RH	Cracked	105.00 F	*105.00 F
25	1		*FRT FENDER INNER COVER LH	Not Necessary	105.00 F	*- F
26	1		*HEADLAMP RH	Broken	680.00 F	*680.00 F
27	1		*HEADLAMP LH	Cracked	680.00 F	*680.00 F
28	1		*FOG LAMP RH	Missing	125.00 F	*125.00 F
29	1		*FOG LAMP LH	Not Necessary	125.00 F	*- F
30	1		*RADIATOR ASSY	Dented	520.00 F	*520.00 F
31	1		*CONDENSOR ASSY	Twisted	530.00 F	*530.00 F
32	1		*FAN SHROUD	Not Necessary	145.00 F	*- F
33	1		*FAN MOTOR	Not Necessary	210.00 F	*- F
34	1		*FAN BLADE	Not Necessary	90.00 F	*- F
35	1		*DISCHARGE HOSE	Not Necessary	265.00 F	*- F
36	1		*SUCTION HOSE	Dented	305.00 F	*305.00 F
37	1		*AIR FILTER HOUSING COMPLETE	Not Necessary	280.00 F	*- F
38	1		*AIR FILTER DUCT	Not Necessary	85.00 F	*- F
39	1		*WIPER PANEL END GARNISH RH	Not Necessary	55.00 F	*- F
40	1		*WIPER PANEL END GARNISH LH	Not Necessary	55.00 F	*- F
41	1		*FENDER REAR END COVER RH	Not Necessary	50.00 F	*- F
42	1		*FENDER REAR END COVER LH	Not Necessary	50.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT CENTRE CROSSMEMBER	Bent	-	*220.00 F
44	1		*FRONT ENGINE MOUNTING BRACKET	Bent	-	*60.00 F
45	1		*FRONT ENGINE MOUNTING	Bent	-	*165.00 F
46	1		*WASHER TANK	Cracked	-	*70.00 F
47	1		*EXPANSION TANK	Cracked	-	*60.00 F
48	1		*RADIATOR LOWER HOSE	Damaged	-	*40.00 F
49	1		*HEADLAMP CHROME MLDG RH	Cracked	-	*90.00 F
50	1		*AIR INTAKE CHAMBER U	Cracked	-	*85.00 F
51	1		*RESONATOR CHAMBER	Cracked	-	*70.00 F
52	1		*FRONT BUMPER LOWER GARNISH	Cracked	-	*95.00 F
53	1		*ABS PUMP ASSY	Dented	-	*1,900.00 F

F=Franchise part.

Sub Total (S\$)	7,720.00	8,770.00
+ Margin on L,N Items 10.00/10.00% (S\$)	772.00	877.00
Total Parts (S\$)	8,492.00	9,647.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	CAR PLATE FRAME (MISSING)	30.00	25.00
2	1	FRONT BUMPER, FENDER INNER COVER & GRILLE GARNISH/PANEL CLIPS (NECESSARY)	200.00	50.00
3	1	FRT CAR PLATE (BENT)	30.00	20.00
Sub Total (S\$)			260.00	95.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,400.00	1,000.00
2	SPRAY PAINT - FRT BUMPER, BONNET X2, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,400.00	1,000.00
3	REFILL - RADIATOR COOLANT	New	80.00	30.00
4	REFILL - AIR COND GAS	New	80.00	30.00
5	ALIGN HEADLAMP/FOG LAMP & TEST WIRING	New	80.00	30.00
6	STRAIGHTEN & ALIGN FRONT CHASSIS MEMBER RH & LH	New	-	250.00
Gross Labour Cost (S\$)			3,040.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >