

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23001670/SQY3Q2**Date:** 23/03/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP000885	
Claimant Vehicle No :	SHD6701E	Insured Vehicle No :	SMY4983B	
Date of Loss:	13/02/2023	Nature of Claim:	TP	Claim No: M2300971

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6701E	Engine No:	65192433223135
Make & Model:	MERCEDES-BENZ E220, 2.2 (A)	Chassis No:	WDD2120012B312593
Reg. Date:	23/03/2016 (Man. Year: 2015)	Odometer:	787892 km
Colour:	White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	225/55R16	Rear Tyre Size:	225/55R16
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,883.92	6,782.44	6,101.48	47.36
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,200.00	2,490.00	710.00	22.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,094.92	9,283.44	6,811.48	42.32
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	16,094.92	6,600.00	9,494.92	58.99
+ GST 8.00/8.00% (S\$)	1,287.59	528.00	759.59	58.99
Nett Amount (S\$)	17,382.51	7,128.00	10,254.51	58.99

INSPECTION

Date of Assignment:	14/02/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/02/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	7.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

Book Value:\$39,450.39

LTA REBATE:\$35,453.00

Nett Value:\$3,997.39

Please take note that repair cost exceeding nett value.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts: 143	MERCEDES-BENZ E220 2.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD6701E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	1,890.00 FL	*1,890.00 FL
2	1		*FRT BUMPER REINFORCEMENT	Not Necessary	1,158.00 FL	*- FL
3	1		*BOOTLID	Repair	2,470.00 FL	*- FL
4	2		*BOOTLID LAMP RH / LH	Not Necessary	1,310.00 FL	*- FL
5	1		*BOOTLID OUTER HANDLE	Not Necessary	87.40 FL	*- FL
6	1		*BOOTLID LOCK	Not Necessary	275.00 FL	*- FL
7	1		*BOOTLID LOCK LOWER CATCH	Not Necessary	35.00 FL	*- FL
8	1		*BOOTLID E220	Necessary	54.30 FL	*54.30 FL
9	1		*BOOTLID SOVEREIGN STICKER	Necessary	25.00 F	*25.00 F
10	1		*BOOTLID MERCEDES STAR	Necessary	45.00 FL	*45.00 FL
11	1		*BOOTLID BLUETEC	Necessary	90.00 FL	*90.00 FL
12	1		*REAR BUMPER	Cracked	1,510.00 FL	*1,510.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	1,150.00 FL	*1,150.00 FL
14	2		*REAR BUMPER LOWER BRACKET RH / LH	Not Necessary	270.00 FL	*- FL
15	2		*REAR BUMPER TOP BRACKET RH / LH	Not Necessary	250.00 FL	*- FL
16	1		*REAR BUMPER CENTRE FRAME	Not Necessary	177.55 FL	*- FL
17	1		*REAR BUMPER TOWING COVER	Scratched	175.00 FL	*175.00 FL
18	1		*REAR BUMPER LOWER COVER	Scratched	325.00 FL	*325.00 FL
19	2		*REAR BUMPER SIDE BEAM RH / LH	Not Necessary	37.30 FL	*- FL
20	2		*REAR BUMPER AIR DUCT RH / LH	Not Necessary	36.60 FL	*- FL
21	1		*REAR END PANEL	Dented	1,380.00 FL	*1,380.00 FL
22	1		*REAR END PANEL INNER GARNISH	Not Necessary	240.00 FL	*- FL
23	2		*TAILLAMP RH / LH	Scratched	1,280.00 FL	*1,280.00 FL
24	1		*REAR TYRE PANEL	Repair	1,280.00 FL	*- FL
25	1		*REVER SENSORS	Scratched	388.00 F	*388.00 F
26	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	15,989.15	8,362.30
- List Item Discount on L Items 20.00/20.00% (\$)	3,105.23	1,579.86
Total Parts (\$)	12,883.92	6,782.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING - FRONT & REAR	New	2,000.00	1,600.00
2	SPRAY PAINTING - FRONT & REAR	New	1,000.00	800.00
3	CHECK LIGHTINGS	New	80.00	30.00
4	R/I REVERSE SENSORS	New	120.00	60.00
Gross Labour Cost (\$\$)			3,200.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >