

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1096G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRKT RH & LH @ \$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER CENTRE MOULDING	CRACKED	451.25	451.25
10	REAR BUMPER COVER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR SMART KEY ANTENNA	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-355.97	-90.25
			1,423.88	361.00
	NETT ITEMS			
1	REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
1	REAR NO. PLATE WITH TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
2	REAR FENDER ADV.STICKER RH / LH @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			820.00	600.00
	GRAND TOTAL		2,705.38	1,260.50

Report Ref No. NS/INC23001675/Sqp3e2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,000.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23001675/Sqp3e2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser