

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|-----------------|-------|----------------------|--|
| | BLUWEL AUTOMO | TIVE SERVICE PTE LTD | | Ref: | CS/TP23001677/Uvy3e2 | |
| | BLK 1 KAKI BUKIT #01-28/53/55/56 (N 417883 | AVE 6 IAIN OFFICE)SINGAPORE | | Date: | 09/03/2023 | |
| | ON BEHALF OF LI | M BUAN TECK DANNY | | Code: | TP149 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | | Veh. Inspected | | SLF 3080A | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 15/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | MAZDA 5 (A) | c.c | | 1998 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | |
| | Chassis No. | JM6CW1071G0124272 | Colour | | GREY | |
| | Odometer | 161265 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | L/H Front Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | R/H Rear Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| | L/H Rear Tyre | 205/55 R16 | PIRELLI | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 11/02/2023 | Inspection Date | е | 15/02/2023 | |
| | Survey held at | Survey held at BLUWEL AUTOMOTIVE SERVICE PL | | | | |
| | BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883 | | | | | |
| 5a. | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days | | | | |