



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET			Ref: CC4/HSB23001690/Upa3q2 Date: 27/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6755Z	Veh. Inspected	SVJ 2637R	
Policy No.	P2478218	Coverage (\$)	0.00	
Claim No.	S3M04JBZ	Excess (\$)	0.00	
Assign From		Assign Date	15/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO EX FORTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KNAFU411MA5162829	Colour	BROWN	
Odometer	248458 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	6 mm	
L/H Front Tyre	195/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/02/2023	Inspection Date	15/02/2023	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	