

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6232R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	3,301.87	-
1	REAR BUMPER LOWER COVER	DENTED	2,013.75	750.75
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	528.75	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	48.00	-
1	REAR BUMPER REVERSE LAMP	NOT NECESSARY	375.00	-
2	REAR BUMPER RETAINER LH / RH @\$87.00	NOT NECESSARY	174.00	-
	LESS 20% DISCOUNT		-1,288.27	-150.15
			5,153.10	600.60
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	NOT NECESSARY	240.00	-
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	BUMPER LINE STICKER (SN)	NECESSARY	40.00	40.00
			330.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		700.00	400.00
	SPRAY PAINTING CHARGE.		400.00	400.00
	TUFF COAT.	NOT NECESSARY	60.00	-
	CHECK WIRING.		60.00	30.00
			1,220.00	830.00
	GRAND TOTAL		6,703.10	1,520.60

RECOMMENDED COST OF REPAIRS (CONFIRMED			1,520.60
--	--	--	----------

Report Ref No. NS/INC23001691/Snp3e2

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser