

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001698/UQP3Q2**Date:** 03/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00112822202

Claimant Vehicle No : SKK5086G **Insured Vehicle No :** YQ2841R

Date of Loss: 13/02/2023 Nature of Claim: TP Claim No: SNM23D201188/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK5086G**

Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAXD46113

Reg. Date: 25/07/2013 (Man. Year: 2013) Chassis No: WVVZZZ16ZDM086426

Colour: Grey Odometer: 199719 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,058.29	3,927.65	10,130.64	72.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	1,730.00	2,140.00	55.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,928.29	5,657.65	12,270.64	68.44
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	17,928.29	4,500.00	13,428.29	74.90

INSPECTION

Date of Assignment: 15/02/2023

Date Inspected: 16/02/2023 Inspected At: 130 BEDOK RESERVOIR ROAD,
#08-1339,EUNOS SPRING
SINGAPORE 470130
Repairer:Zoom Autowerks Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2023)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK5086G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented / Bent	1,178.30 FL	*1,178.30 FL
2	1		*REAR BOOT HINGES	Not Necessary	494.00 FL	*- FL
3	1		*REAR BOOT LAMPS (O/S CRACKED / N/S SCRATCHED)	O/SNotConsistentWithTheImpact	386.40 FL	*193.20 FL
4	1		*REAR BOOT LOCK	Not Necessary	198.00 FL	*- FL
5	1		*REAR BOOT LOGO	Not Necessary	125.00 FL	*- FL
6	1		*REAR BOOT RUBBER	Not Necessary	354.00 FL	*- FL
7	1		*REAR BOOT JETTA EMBLEM	Necessary	91.00 FL	*91.00 FL
8	1		*REAR BOOT TSI EMBLEM	Necessary	76.00 FL	*76.00 FL
9	2		*REAR TAILLAMPS	Not Necessary	1,398.00 FL	*- FL
10	1		*REAR END PANEL	Repair	1,339.00 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Not Necessary	215.00 FL	*- FL
12	1		*REAR BUMPER	Dented / Deformed	1,430.00 FL	*1,150.00 FL
13	2		*REAR BUMPER BRACKETS	Not Necessary	250.00 FL	*- FL
14	1		*REAR BUMPER INNER SPONGE	Not Necessary	125.00 FL	*- FL
15	1		*REAR BUMPER LOWER DIFFUSER	Torn	785.00 FL	*380.00 FL
16	1		*REAR BUMPER REFLECTORS	N/S Cracked / O/SNot Necessary	136.00 FL	*68.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Repair	767.00 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	172.00 FL	*- FL
19	2		*REAR BUMPER PDC SENSORS	Serviceable	530.00 FL	*- FL
20	2		*FRONT HEADLAMPS	Not Necessary	1,737.60 FL	*- FL
21	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	151.60 FL	*- FL
22	1		*FRONT GRILLE WTIH CHROME ASSY	Not Necessary	1,148.00 FL	*- FL
23	1		*FRONT GRILLE LOGO	Not Necessary	165.00 FL	*- FL
24	1		*FRONT BUMPER	Deformed / Torn	1,072.00 FL	*1,072.00 FL
25	2		*FRONT BUMPER FOG LAMPS	Not Necessary	465.60 FL	*- FL
26	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	312.00 FL	*- FL
27	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	215.00 FL	*- FL
28	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	81.60 FL	*- FL
29	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
30	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
31	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
32	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,598.10	4,348.50
- List Item Discount on L Items 10.00/10.00% (\$)	1,539.81	420.85
Total Parts (\$)	14,058.29	3,927.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECL WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
6	TO APPLY UNDERCOATING	New	200.00	30.00
7	PANEL BEATING	New	1,600.00	500.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,870.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >