

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/C+123001698/4923

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKK50866

at Workshop m/s

200M

of

Insured:

YQ2841R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

814k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1356

Date:

Person Contacted:

Vehicle: IN / OUT

27/12/23 17459097

Veh No:

SKK50866

Yr Regn:

25/07/13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Volkswagen

Jetta

c.c

1390

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

199719

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ16ZDM086426

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

roadstone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/02/23

D.O.I.

16/2/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Des

27/12/23

Bal 5m. Not 84903
1/5 @ 4500 in bond E.G. CRAD 13428.29, 75%)

Date/Time, File Pass to?

1) 28/12/23

Date/Time, File Return to?

2)

: Preli. Report

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

MED-TP

Lump Sum / I.B.I. (\$

4500

Not Authorised

22 February 2023

her
16/2/23

1/5 @ 4500/
5 days.

REG NO.: SKK 5086 G
MAKE/MODEL: VOLKSWAGEN JETTA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear boot lid <i>22/2erf</i>	\$ 1,178.30 ✓
2	Rear boot hinges <i>11</i>	\$ 494.00 X
2	Rear boot lamps <i>mis scr o/s crn alc</i>	\$ 193.20 386.40 1pc
1	Rear boot lock <i>11</i>	\$ 198.00
1	Rear boot logo <i>11</i>	\$ 125.00 X
1	Rear boot rubber <i>11</i>	\$ 354.00 X
1	Rear boot "JETTA" emblem <i>her</i>	\$ 91.00 ✓
1	Rear boot "TSI" emblem <i>her</i>	\$ 76.00 ✓
2	Rear taillamps <i>11</i>	\$ 1,398.00 X
1	Rear end panel <i>11</i>	\$ 1,339.00 X
1	Rear end panel inner garnish <i>11</i>	\$ 215.00 X
1	Rear bumper <i>22/2e</i>	\$ 1150 1,430.00 ✓
2	Rear bumper brackets <i>11</i>	\$ 250.00 X
1	Rear bumper inner sponge <i>11</i>	\$ 125.00 X
1	Rear bumper lower diffuser <i>11</i>	\$ 785.00 ✓
2	Rear bumper reflectors <i>mis crn o/s crn</i>	\$ 68 136.00 1pc
1	Rear bumper reinforcement <i>11</i>	\$ 767.00 X
2	Rear bumper side retainers <i>11</i>	\$ 172.00 X
2	Rear bumper PDC sensors <i>scr</i>	\$ 530.00 X
2	Front headlamps <i>11</i>	\$ 1,737.60 X
2	Front headlamp lower brackets <i>11</i>	\$ 151.60 X
1	Front grille with chrome assy <i>11</i>	\$ 1,148.00 X
1	Front grille logo <i>11</i>	\$ 165.00 X
1	Front bumper <i>re / 1011</i>	\$ 1,072.00 ✓
2	Front bumper fog lamps <i>11</i>	\$ 465.60 X
2	Front bumper fog lamp covers <i>11</i>	\$ 312.00 X
1	Front bumper lower grille <i>11</i>	\$ 215.00 X
2	Front bumper side retainers <i>11</i>	\$ 81.60 X
		\$ 15,398.10
	Less 10%	\$ 1,539.81
		\$ 13,858.29

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	neu	\$	50.00	/
1	Rear number plate		\$	50.00	X
1	Front bumper clip (1 set)	neu	\$	50.00	/
1	Front number plate with holder	3enf	\$	50.00	40
			\$	200.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
3	To remove and refit inner garnishes.	\$	180.00	60
4	To remove and refit rear reverse sensor.	\$	150.00	50
5	To transfer boot lid mechanism and wiring assembly.	\$	80.00	60
6	To apply undercoating.	\$	200.00	30
7	Panel beating.	\$	1,600.00	500
8	To re-spray painting on the affected areas.	\$	1,500.00	1000
		\$	3,870.00	

GRAND TOTAL :

\$ 17,928.29

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4208-5
102
3787.65
140
1730
5657.65
4526