

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre



330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

Por No.	ESTIMATE	GST Reg No : MR-8500111-			
Reg No : 197701469G	Owner Name & Vehicle Info				
Invoice Name & Address	Cust No/Name	KCV09712/Ms LIM			
Ms LIM	Reg No/Reg Date	SGY6688L*CS5P/ 19/11/201			
16 CANBERRA DRIVE	Date In/Mileage	13/02/2023/ 81082			
#14-35	Chassis No	MMBSTA13AJH004340 3A92UHK0266 MIT/18MY ATTRAGE 1.2 CVT			
SINGAPORE 768097	Engine No				
Contact No Mobile: 84181688	Make/Model				
Contact No Mobile: 04101000	Colour/Trim	UO1 TITANIUM GREY M/ BK BLACK			

Account No	Terms	Date/Time Pri	nted	CSE	Operator		WIP No		April 100 miles	
CTP00040	Cash	14/02/2023/		LER	972 / Mars Ler		14592	No.		The second secon
L1P00040	Cusii	Description of	of Goods	/ Services		Qty	Unit Price	Disc%	An	nount
Z TEXT	AND DESCRIPTION OF	- Decempos			0 . 104	4	30 8			
ACCIDENT	ON 11/0	2/2023 ALONG J	IALAN MA	S PUTEH	Sundry	- Ψ	00 //			
OWNER CLA	AIMING T	HIRD PARTY			THE STATE OF		,			
REQUIRED		MENT CAR								
TP # SJU2	2841Y	TP INS: ALLI	ANZ		LKK Auto Con	sultants hence n		-	80	160.00
M SUNDRY	ATAL ANT	MAT ON DEAD D	ODV VIT							
TO APPLY SEALANT KIT ON REAR BODY KIT F DNT88000									rves+ 100.00	
E PNT88000	AND TEC	T REAR REVERSE	CENCOD		- IV weighty carrie	Died Continue to the store on			_	
	AND TES	I KEAR KEVERSE	. SENSON		A MINISTER AND THE PARTY OF THE	SUDMATE In condition and			?	220.00
E PNT88000	V DEAD D	EVERSE SENSOR	(NETT)		No illegal modific	y is on a "Without Pri	ejudice" basis		200	
E PNT88000	I KLAK KI	LAFINSE SENSOR		> 4 7 j	Supplementary is	approprial from Instanta	A		?	640.00
TO REMOVE	AND RE	INSTALL TRIMMI	NG AND	CAPERTING	TO CIVE WAY ACCES	approval from mauca	nce Company			
REPAIR ON	N REAR A	CCIDENT AFFECT	ED AREA	5) [5]	Admonissiped by R	117	7			1000 00
E PNT88000					Signature:	848/1997	- 1		640	1920.00
TO REPLAC	E REAR	BODDY KIT, ETC			Date:					
-TO REPAI	R REAR I	BUMPER AND REA	R END P	ANEL						
STRAIGHTE	N, REFORM	ALIGN ON REA	R ACCID	ENT AFFECT	TED AREAS				C/ A	2200.00
E PNT98000									350	2200.00
SPRAY PAI	NTING ON	REAR ACCIDEN	IT AFFEC	TED AREAS						280.00
A 10028901			HOTHO		AND CLEAD TROUBL	E CODE			Nott	200.00
	T DIAGNO	STIC CHECK ON	USING	MOI LESTER	R AND CLEAR TROUBL	L CODE			80	100.00
A 54900099	TNO 0 FI	COTOTONI CVCT	EM							100.00
HECK WIR M BODYKITS	ING & EL	ECTRICAL SYST	CIT			1.00	1643.00	00.00	/	1643.00
The state of the state of the	HMDED					10.00		00.00		40.00
D DDACKET D	D DIMDED	. TH				1.00		00.00		25.00
BRACKET, R	R RIMPER	RH			1111	1.00	25.00	00.00	1?	25.00
M REFLECTOR	IN DOME LIN	,,,,,,		- 164	on LICIC	1.00		00.00		20.00
M BUZZER.KE	YLESS OP	FRATIO RSURVE	YOR NAM	: i	91	1.00		00.00	Strategy .	94.00
		RH ERATIO, RAURVE	VOR SIGN	NATURE :	7 . 2 .			•		
		30111	171	2/23	1230pm					
		DATE		010	010					
- Company of the Comp	and the same of the same of			2 day	5					
Confirm & ac	cepted by	y REMA	RKS:—	0						
Nett						tt		7,467.0		
						8% GST on				597.3
						5, 35, OII	, , , , ,			
						т	otal Payab	1e		8,064.3
		1000	A. Den							
Authorized s	ignatory	and company st	amn							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional costs and are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional costs are discovered. any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheeve you must also some a started and the source of receiving the started and the source of receiving the source of receiving the source of receiving the started and the sta cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.