



Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Co Reg No : 197701469G		ESTIMATE		U31 Reg No	
Invoice Name & Address			Owner Name & Vehicle Info		
Ms LIM 16 CANBERRA DRIVE #14-35 SINGAPORE 768097 Contact No Mobile: 84181688			Cust No/Name	KCV09712/Ms LIM	
			Reg No/Reg Date	SGY6688L*CS5P/ 19/11/201	
			Date In/Mileage	13/02/2023/ 81082	
			Chassis No	MMBSTA13AJH004340	
			Engine No	3A92UHK0266	
			Make/Model	MIT/18MY ATTRAGE 1.2 CVT	
			Colour/Trim	U01 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	14/02/2023/ 11:00	LER	972 / Mars Ler	14592
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
Z TEXT ACCIDENT ON 11/02/2023 ALONG JALAN MAS PUTEH OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SJU2841Y TP INS: ALLIANZ					
M SUNDRY TO APPLY SEALANT KIT ON REAR BODY KIT					
E PNT88000 TO CHECK AND TEST REAR REVERSE SENSOR					
E PNT88000 TO SUPPLY REAR REVERSE SENSOR (NETT)					
E PNT88000 TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000 TO REPLACE REAR BODDY KIT,ETC -TO REPAIR REAR BUMPER AND REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
A 10028901 TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE					
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM					
M BODYKITS	1.00	1643.00	00.00		1643.00
P CLIP,RR BUMPER	1.00	4.00	00.00		40.00
P BRACKET,RR BUMPER,LH	1.00	25.00	00.00		25.00
M BRACKET,RR BUMPER,RH	1.00	25.00	00.00		25.00
M REFLECTOR	1.00	20.00	00.00		20.00
M BUZZER,KEYLESS OPERATIO,RR	1.00	94.00	00.00		94.00
SURVEYOR NAME: Irfan Lick					
SURVEYOR SIGNATURE: [Signature]					
DATE: 17/2/23 1230pm					
REMARKS: 3 days P/P					
Confirm & accepted by					
				Nett	7,467.00
8% GST on				7467.00	597.36
Total Payable					8,064.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms LIM	Cust No/Name	KCV09712/Ms LIM
16 CANBERRA DRIVE	Reg No/Reg Date	SGY6688L*CS5P/ 19/11/201
#14-35	Date In/Mileage	10/05/2023/ 81082
SINGAPORE 768097	Chassis No	MMBSTA13AJH004340
Contact No Mobile: 84181688	Engine No	3A92UHK0266
11/05/	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	12/05/2023/ 12:07	LER	972 / Mars Ler	14592
Description of Goods / Services					Qty Unit Price Disc% Amount
Z TEXT SUPPLEMENTARY ITEM M SUNDRY SUNDRIES					NEC ✓ 30.00
Estimate					

Confirm & accepted by

Supplementary

Authorized signatory and company stamp

	Nett	30.00
8% GST on	30.00	2.40
	Total Payable	32.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.