

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/HSB23001704/Rwp3m4 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 23/02/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: ANG YVONNE Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. SHC 7306L FBD 9194U Insured Veh. Veh. Inspected VFX/P2419140 0.00 Policy No. Coverage (\$) S2M04GHY 0.00 Claim No. Excess (\$) ANG YVONNE 15/02/2023 **Assign Date** Assign From Vehicle Particulars & Condition 2. HONDA WAVE 125 Make & Model C.C **HIDDEN** Engine No. Year of Reg. 2009 NF125ST0027750 Chassis No. Colour **BLUE** Odometer 93166 KM **IN ORDER** Steering **IN ORDER** SPORTS RIM Modification **Brakes** FAIR General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre MICHELIN 70/90-17 3 mm L/H Front Tyre mm 90/80-17 **MICHELIN** R/H Rear Tyre 3 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. 5. **General Information** 13/12/2022 **Inspect Date / Time** 15/02/2023 (01:02 PM) **Accident Date** Survey held at THONG SHENG MOTORS TRADING BLK 7 PIONEER ROAD NORTH, OFF LOK YANG WAY, #01-50 SINGAPORE 628459. 5a. **Remarks** A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/HSB23001704/Rwp3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser