

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS23001706/UPA3Q2**Date:** 20/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002535621
<b>Claimant Vehicle No :</b>	GBB9745R	<b>Insured Vehicle No :</b>	SJY81R
Date of Loss:	07/02/2023	Nature of Claim:	TP
		Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBB9745R</b>	Engine No:	1KD2042575
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y50K201321
Reg. Date:	27/12/2010 (Man. Year: 2010)	Odometer:	468179 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Triangle 6 mm	Rear Left Side:	APLUS 6/6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	APLUS 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,730.00	2,400.00	2,330.00	49.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,100.00	850.00	43.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,680.00</b>	<b>3,500.00</b>	<b>3,180.00</b>	<b>47.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,680.00</b>	<b>2,800.00</b>	<b>3,880.00</b>	<b>58.08</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,202.00</b>		

**INSPECTION**

Date of Assignment:	15/02/2023	
Date Inspected:	15/02/2023 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9745R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAILGATE	Dented / Bent	2,950.00 FS	*1,800.00 FS
2	1		*REAR TAILGATE LOCK BAR	Repair	380.00 FS	*- FS
3	1		*REAR END PANEL	Bent	1,400.00 FS	*600.00 FS
					<b>Total Parts (S\$)</b>	<b>4,730.00</b>
						<b>2,400.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	600.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	500.00
3	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,950.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >