6/5/23, 1:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23001708/SWY3Q2

M2300982

Date: 05/06/2023

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MN000293

Claimant Vehicle No :

SHD3223M

Insured Vehicle No: SLP356Y

Date of Loss: 13/02/2023

Nature of Claim: TP Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3223M

Make & Model: HYUNDAI I40, 1.7 D CRDi (A) Engine No: D4FDGU674246

Reg. Date: 30/06/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU091601

Colour: Blue Odometer: 870483 km

Engine Capacity:
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1685 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,378.72	692.40	686.32	49.78
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	560.00	90.00	13.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,039.72	1,263.40	776.32	38.06
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,039.72	1,000.00	1,039.72	50.97
+ GST 8.00/8.00% (S\$)	163.18	80.00	83.18	50.97
Nett Amount (S\$)	2,202.90	1,080.00	1,122.90	50.97

INSPECTION

Date of Assignment: 15/02/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 15/02/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/5/23, 1:59 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jun 2023)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3223M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cut	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER UNDER COVER	Not Necessary	288.00 FL	*- FL
4	1		*REAR BUMPER BEAM	Not Necessary	428.40 FL	*- FL
5	1		*REAR BUMPER SPONGE	Not Necessary	119.50 FL	*- FL
6	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
7	1		*ADVERTISEMENT LOGO- FENDER	Necessary	200.00 F	*200.00 F
F=Fra	anchise	part. L=ListIte	mDisc.	Sub Total (S\$)	1,660.90	803.00
			- List Item Discount o	on L Items 20.00/20.00% (S\$)	282.18	110.60
				Total Parts (S\$)	1,378.72	692.40
			Report was unsubmitted of	during this print-out		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVFE/REFIX REVERSE SENSOR	New	50.00	30.00
		Gross Labour Cost (S\$)	650.00	560.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >